


|               |             |                  |                  |
|---------------|-------------|------------------|------------------|
| Make:         | Volkswagen  | Model:           | Tiguan           |
| Body Style:   | SUV         | Year:            | 2018             |
| Rego No.:     | LSP598      | Rego Expiry:     | 18 May 2026      |
| WoF Expiry:   | 16 Sep 2026 | Odometer:        | 176,941 Kms      |
| Good No.:     | 25991042    | VIN:             | WVGZZ5NZJM130957 |
| Next Service: | 183,716     | Service History: | No               |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Stone chips in the windscreens one has legs,

Conditions During Body Inspection

Dry

**Under Carriage and Under Bonnet Inspection Comments**

Oil leaks,

**Interior Comments**

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

**General Comments**

4WD,

|                                   |                              |                             |     |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry                          |                             |     |
| Engine Timing Mechanism           | Timing Chain                 |                             |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by:                     | Jesse Roberts                |                             |     |
| Published by:                     | Jesse Roberts                |                             |     |
| Inspection Date:                  | 25 Nov 2025                  |                             |     |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

|   | OK | Requires Attention | N/A |
|---|----|--------------------|-----|
| <b>Engine</b>                                       |    |                    |     |
| Oil level   | ✓  |                    |     |
| Smoke & fumes                                       | ✓  |                    |     |
| Engine performance                                  | ✓  |                    |     |
| Noise   | ✓  |                    |     |
| Coolant condition                                   | ✓  |                    |     |
| Cooling performance                                 | ✓  |                    |     |
| Radiator / Hoses (visual)                           | ✓  |                    |     |
| <b>Transmission</b>                                 |    |                    |     |
| Operation   | ✓  |                    |     |
| Noise   | ✓  |                    |     |
| Clutch  |    |                    | ✓   |
| CV joints   | ✓  |                    |     |
| Wheel bearings                                      | ✓  |                    |     |
| <b>Brakes</b>                                       |    |                    |     |
| Performance   | ✓  |                    |     |
| Hand brake  | ✓  |                    |     |
| <b>Tyres (lowest observed tread depth of tyres)</b> |    |                    |     |
| Left front  |    | 2.3 mm             |     |
| Right front   |    | 3.3 mm             |     |
| Left rear   |    | 2.3 mm             |     |
| Right rear  |    | 2.6 mm             |     |
| Spare   |    | Yes                |     |
| <b>Suspension</b>                                   |    |                    |     |
| Suspension performance                              | ✓  |                    |     |
| Steering performance                                | ✓  |                    |     |
| Shock absorbers                                     | ✓  |                    |     |
| <b>Air Conditioning / Heater</b>                    |    |                    |     |
| Operation   | ✓  |                    |     |
| <b>Electrical / Accessories</b>                     |    |                    |     |
| Head lights   | ✓  |                    |     |
| Tail lights   | ✓  |                    |     |
| Indicators  | ✓  |                    |     |
| Dashboard warning lights                            | ✓  |                    |     |
| Wipers (front & rear)                               | ✓  |                    |     |
| Window winder FL                                    | ✓  |                    |     |
| Window winder FR                                    | ✓  |                    |     |
| Window winder RL                                    | ✓  |                    |     |
| Window winder RR                                    | ✓  |                    |     |
| Rear view mirrors                                   | ✓  |                    |     |
| Radio (basic test only)                             | ✓  |                    |     |
| CD (basic test only)                                |    |                    | ✓   |
| Number of keys                                      | 1  |                    |     |
| Central locking                                     | ✓  |                    |     |
| Remote locking                                      | ✓  |                    |     |
| Sat. nav. (basic test only)                         | ✓  |                    |     |
| Reversing camera                                    | ✓  |                    |     |

SIGNATURE \_\_\_\_\_