

Basic Condition Guide

•	Report ID:	25,991,074	Version:	2
	Created:	12 Dec 2025		

Make:	Holden	Model:	Colorado			011	Requires	B1/8
Body Style:	Utility	Year:	2018	OK Engine			Attention	N/A
Rego No.:	LDW454	Rego Expiry:	06 Feb 2026	Oil level		· ·		
WoF Expiry:	02 Feb 2026	Odometer:	152,234 Kms	Smoke & fumes		V		
Good No.:	ood No.: 25991074 VIN: MMU148EK0JH61797		MMU148EK0JH617970	Engine performance		-		
Next Service: 152000 Service History: No		No	Noise		1		\vdash	
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Coolant condition			
					rformance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
					Radiator / Hoses (visual)			
ey = Scratch R	Dust C C	Transmission						
	= Rust $C = CT =$ Paint defect $P = P$	Operation		V	<u> </u>			
			Noise		1			
s sc	S	P SC S SC	Clutch				1	
			CV joints		1			
			S	Wheel bearings		1		
s sc				Brakes				
	19/1			Performance		'		
s sc					Hand brake			
s sc	18		Tyres (lowe	Tyres (lowest observed tread depth of tyres)				
				Left front 5.0 m				
			S SC	Right front		5.3 mm		
				Left rear		3.0 mn		
s sc		s sc ssc	SSC	Right rear		4.4 mm		
ote: some defects	and blemishes may not be	e displayed in the diagra	m	Spare	Spare Yes			
Body Inspecti	on Comments			Suspensio	n			
_	s on windscreen			Suspension	n performance	'		
Minor stonechip	os on windscreen			Steering pe	erformance	~		
				Shock abso	orbers	'		
Conditions Du	ring Body Inspection		Air Conditioning / Heater					
Under Carriag	je and Under Bonnet	Inspection Comm	ients	Operation 🗸				
Rear wheel driv	re			Electrical /	'Accessories			
				Head lights	5		/	
				Tail lights		'		
Interior Comments						1		
Seats:	Good			Dashboard	warning lights	~		
Carpets:	pets: Good			Wipers (fro	nt & rear)	/		
Panels:	: Good			Window w	inder FL	•		
Dashboard: Good					inder FR	/		
General Comr	ments		Window w	inder RL	'			
Due for service				Window w	inder RR	'		
Central locking Only has passe				Rear view r	mirrors	~		
J. 1140 P4636	gor noor mat			Radio (basi	c test only)	~		
Road Conditions During Test Drive Dry					est only)			1
Engine Timing Mechanism Cambelt					keys	1	•	
Evidence of Cam Belt Replacement Yes No Kms				Central loc	king		V	
						_		—

I have read and understood this condition guide:

Inspection Date: 28 Nov 2025

Inspected by:

Published by:

Cameron Senior-Arnold

Kendal Slight

NAME

SIGNATURE

Sat. nav. (basic test only)

Remote locking

Reversing camera

1