

Report ID:	25,991,088	Version:	1
Created:	28 Nov 2025		

Ea Th	rner	C Basi	c Condition Guide	neport ib.		ve	TSIOH:	
		<u> </u>		Created:	28 Nov 2025			
Make:	Holden	Model:	Colorado			01/	Requires	
Body Style:	Utility	Year:	2017	Engine		OK	Attention	N/A
Rego No.:	LBU701	Rego Expiry:	18 Dec 2025	Oil level		V		
WoF Expiry:	11 Dec 2025	Odometer:	161,253 Kms	Smoke & fu	ımor	V		
Good No.:	25991088	VIN:	MMU148EK0JH628763	Engine per		V		
Next Service:	163000	Service History:	Yes	Noise	Torriance	V		
ote: This report is n	ot a warranty			Coolant co	ndition	1		-
his report is a guide o liagnostic testing und	only. Consideration is made lertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a	Cooling pe		V		-
	ction prior to purchase and				Hoses (visual)	V		
ey				Transmiss			<u> </u>	
	Rust C=C		3		ion	V	l	
D = Dent PT	= Paint defect $P = Pi$	in dent SC = Sto	ne Chips	Operation		-		
s sc	S	S SC S SC	SSC	Noise		/		_
				Clutch				/
	\sim		S	CV joints		/		-
s sc				Wheel bea	rings	'		
$-\!$	8			Brakes				
	M = M		sc	Performan	ce	/		
				Hand brake	e	/		
sc			NL HIB	Tyres (lowest observed tread depth of tyres)				
\mathcal{A}		/		Left front				5.9 mr
			S SC	Right front	:			6.1 mr
	\leq			Left rear				4.8 mr
S SC S SC S SC S SC								4.8 mr
lote: some defects a	nd blemishes may not be	displayed in the diagra	ım	Spare Yes				
Body Inspectio	n Comments			Suspensio	n			
Minor stonechips	s on windscreen			Suspension	n performance	/		
				Steering pe	erformance	'		
				Shock abso	orbers	1		
Conditions During Body Inspection Dry				Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments				Operation		'		
Rear wheel drive					Electrical / Accessories			
				Head light:	S	'		
				Tail lights		1		
Interior Comme	ents			Indicators		1		
Seats:	Good			Dashboard	l warning lights	1		
	Good			Wipers (fro		1		
	Good			Window w		1		†
	Good			VVIIIGOVVVV	HIGCHIL			

	Interior Comments			
	Seats:	Good		
	Carpets:	Good		
	Panels:	Good		
	Dashboard:	Good		
General Comments		nents		

Missing both rear floor mats

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	153,000 Kms
Inspected by:	Cameron Senior-	Arnold		
Published by:	Cameron Senior-	Arnold		
Inspection Date:	28 Nov 2025			

SIGNATURE		

1

1

1

1

1

1

Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

I have read	and	und	erstoc	O
this condit	ion g	guide	: :	