

•	Report ID:	25,991,543	Version:	1
	Created:	11 Dec 2025		

	ОК	Requires Attention	N/A
Engine			-
Oil level	✓		
Smoke & fumes	✓		
Engine performance	/		
Noise	✓ ✓		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			/
CV joints	/		
Wheel bearings	~		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		1	.7 mm
Right front		2	2.5 mm
Left rear			2.0 mm
Right rear			2.0 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		<u> </u>	
Operation	✓		
Electrical / Accessories			
Head lights	/		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	/		
Window winder FL	V		
Window winder FR	~		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	/		
CD (basic test only)	✓		
Number of keys	1		
Central locking	/		
Remote locking	✓		
Sat. nav. (basic test only)			/
Reversing camera			/


Make:	Toyota	Model:	Aqua
Body Style:	Hatchback	Year:	2015
Rego No.:	PWD131	Rego Expiry:	01 May 2025
WoF Expiry:	18 Dec 2024	Odometer:	186,893 Kms
Good No.:	25991543	VIN:	7AT0H65YX23460906
Next Service:	167000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Conditions During Body Inspection Dry	Under Carriage and Under Bonnet Inspection Comments				
	Conditions During Body Inspection	Dry			

Front wheel drive

Interior Comments			
Seats:	Stains, Good		
Carpets:	Drivers floor torn, good		
Panels: Good			
Dashboard:	Good		

Due for a service Windscreen cracked

General Comments

Battery flat

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jaykib Collins	
Published by:	Jesse Roberts	
Inspection Date:	03 Dec 2025	

have read and understood
this condition quide

NAME			

SI	GN	IA.	ΓU	RF