

•	Report ID:	25,997,688	Version:	2
	Created:	01 Dec 2025		

Ga Ti	nuel	S Basi	c Condition Guide	Created:	01 Dec 2025	ve	131011.	
Make:	Toyota	Model:	Hilux			ОК	Requires Attention	N/A
Body Style:	Utility	Year:	2019	Engine				
Rego No.:	MHA812	Rego Expiry:	30 Jan 2026	Oil level		<b>'</b>		
WoF Expiry:	03 Aug 2026	Odometer:	150,879 Kms	Smoke & fu	ımes	1		
Good No.:	25997688	VIN:	MR0JA3DDX00345621	Engine per	formance	1		
Next Service:	156,000 kms	Service History:	Yes	Noise		1		
Note: This report is not a warranty				Coolant co	ndition	1		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					rformance	1		
					Hoses (visual)	1		
<b>Key</b> S = Scratch R	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmission				
	T = Paint defect P = Pi		•	Operation		1		
D.D.CO		20.0		Noise		1		
DPSC		D P S SC	PSD	Clutch				1
			P	CV joints				~
				Wheel bea	rings	1		
SC W				Brakes				
PSC				Performan	ce	V		
				Hand brake	e	~		
				Tyres (lowest observed tread depth of tyres)				
SDP			Left front		8.5 mn			
			Right front		9.5 mm			
			Left rear		9.0 mr			
SC		S P S	SPSC	Right rear		9.0 mr		
Note: some defects	and blemishes may not be	displayed in the diagra	nm	Spare		Yes		
Body Inspecti	on Comments			Suspensio	n			
	illars, tailgate badge ir	glovebox		Suspension	n performance	1		
Sill step plates worn/scratched.  Minor dents and scratches inner wheel arches.			Steering pe	erformance	/			
Willion donto an	a solutiones limel whe	or drones.		Shock abso	orbers	/		
Conditions Du	ring Body Inspection		Dry	Air Condit	ioning / Heater			
Under Carriag	e and Under Bonnet	Inspection Comm	nents	Operation		1		
				Electrical /	'Accessories			
				Head lights	5	<b>/</b>		
				Tail lights		/		
Interior Comn	nents			Indicators		<b>'</b>		
Seats:	Good			Dashboard	l warning lights	<b>'</b>		
Carpets:	Good			Wipers (fro	nt & rear)	<b>'</b>		

Interior Comm	Interior Comments			
Seats:	Good			
Carpets:	Good			
Panels: Good				
Dashboard: Holes in centre console				
General Comments				

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Dean Sinclair	
Published by:	Kate Gibson	

I have read and understood	
this condition guide:	NAN

Inspection Date: 28 Nov 2025

NAME			

SIGNATURE		

1

1

1 1

3

1

1

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)