

Report ID:	25,998,605	Version:	1
Created:	18 Mar 2026		


Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2021
Rego No.:	NHB912	Rego Expiry:	15 May 2026
WoF Expiry:	28 Feb 2026	Odometer:	159,376 Kms
Good No.:	25998605	VIN:	MMAJLKL10MH008684
Next Service:	171,407 kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left and right cab corners chips, minor dents and scratches, chips left A pillar tailgate badge needs refitted, chips in CVA area of windscreen, dents right cant rail, Chips left rear step plate, right front step plate worn chips and scratches left front step plate, chips right A pillar

Conditions During Body Inspection: Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	right front seat base pad and headrest torn
Carpets:	Good
Panels:	Average
Dashboard:	Good

General Comments

Roof rack end clip missing, left rear interior door seal minor tear
 Right rear interior door seal minor tear

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Dean Sinclair
Published by:	Dean Sinclair
Inspection Date:	18 Mar 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			7 mm
Right front			7 mm
Left rear			5 mm
Right rear			5 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____