

Basic Vehicle Condition Guide

Report ID: 26,042,849


Version: 10

Created: 17 Mar 2025

Make: Model: HS MG **Body Style:** SUV Year: 2023 Registration: QGZ672 Reg Expiry: 24 Apr 2025 **Odometer:** WoF Expiry: **Good No:** 23 Nov 2026 44,554 Kms 26042849 VIN: LSJA2439XNN111034 **Next Service:** 50,000kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Dry

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Left & right side dashboard heater air vents have glue residue on top part of vent housing.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young Date: 14 Mar 2025

| | Pass | Fail | N/A |
|--------------------------------------|--|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 6 | .0 | mm |
| Right front | 6.0 | | mm |
| Left rear | 3.2 | | mm |
| Right rear | 4.0 | | mm |
| Spare | N/A | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | 1 |
| Operation | V | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | \(\times \) \(\t | | |
| Window winder FR | <i>'</i> | | |
| Window winder RL | V | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| | ~ | | |
| Radio (basic test only) | | | |
| CD (basic test only) Number of keys | 1 | | |
| | 1 | | |
| Central locking | - | | |
| Remote locking | V | | |
| Sat. Nav. (basic test only) | ' | | |
| Reversing camera | ' | 1 | 1 |

I have read and understood this condition guide.

Name:

Signature: