

Left door mirror adjust motor for left-right is not operating.

**Road Conditions During Test Drive:** 

Evidence of Cam Belt Replacement:

**Engine Timing Mechanism:** 

Yuki Itohara Inspected by: I have read and understood this condition guide. Name: .....

Dry

Not Applicable

Kms:

**Timing Chain** 

07 Apr 2025 Date:

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Signature: .....

1

V

2 V

V

1

V

~