

Basic Vehicle Condition Guide

Report ID: 26,043,612


Version: 1

Created: 08 Apr 2025

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2021 Registration: NPE866 Reg Expiry: 27 Apr 2025 WoF Expiry: **Odometer:** 15 Jul 2025 119,604 Kms **Good No:** 26043612 VIN: MMAJLKL10MH019057 Next Service: 132,500kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Hole in centre of front grille & chrome badge is missing. Left side of front bumper is not fitting properly. Right side of rear bumper has been pushed into rear guard.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

General Comments

Engine noise under acceleration. Holes in fabric on base pad of drivers seat. Hole in carpet in right front foot well area.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young

e. cate			
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	ν ν		
Performance	~		
Noise		~	
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4	.5	mm
Right front	4.5		mm
Left rear	4.0		mm
Right rear	3	.5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V		
Window winder FR Window winder RL	<u> </u>		
	'		
Window winder RL			
Window winder RL Window winder RR Rear view mirrors	v		
Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	ン ン ン		<i>V</i>
Window winder RL Window winder RR Rear view mirrors	ン ン ン		V
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	<i>V V V</i>		V
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	<i>V V V</i>		V
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	<i>V V V</i>		V

08 Apr 2025

Date:

I have read and understood this condition guide. Name: Signature: Signature: