

Basic Vehicle Condition Guide

Report ID: 26,043,620


3 Version:

30 Apr 2025 Created:

Make: Model: Hyundai Accent **Body Style:** Hatchback Year: 2019 Registration: MQE407 Reg Expiry: 29 Jun 2025 **Odometer:** WoF Expiry: **Good No:** 25 Dec 2025 63,645 Kms 26043620 VIN: KMHCT51BTKU398651 **Next Service:** 74,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Average	

General Comments

Left side boot parcel tray cord is missing. Minor scratches in right side of dashboard.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

08 Apr 2025 Jason Young Inspected by: Date:

Name:

_				
Pass	Fail	N/A		
Engine Oil level				
~				
~				
~				
~				
Cooling System				
~				
~				
~				
Transmission				
~				
	~			
		~		
~				
~				
Brakes				
~				
~				
Tyres (lowest observed tread depth of tyres)				
5	.0	mm		
6.0		mm		
6	.0	mm		
5.0		mm		
	Yes			
Suspension				
>				
~				
~				
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
~				
~				
~				
>				
~				
~				
~				
~				
~				
~				
~				
~				
2	_			
~				
~				
		~		
~				
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	****		

Signature: