

Basic Condition Guide

Report ID:	26,049,258	Version:	3
Created:	19 Nov 2025		

		—		Created:		
Make:	Suzuki	Model:	Swift			
Body Style: Hatchback		Year:	2022	Engine		
Rego No.:	PAZ693	Rego Expiry:	02 Feb 2026	_		
WoF Expiry:	02 Dec 2026	Odometer:	22,507 Kms	Oil level Smoke & fun		
Good No.:	26049258	VIN:	JSAAZC83S00405358			
Next Service:	32,700kms	Service History:	Yes	Engine perfo		
Note: This report is	Coolant cond					
	This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a					
	ection prior to purchase and			Cooling perf		
Key				Radiator / Ho		
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips				Operation		
SC		S D		Noise		
				Clutch		
			S	CV joints		
W				Wheel bearing		
\sim ρ	18			Brakes		
1			SC	Performance		
				Hand brake		
sc				Tyres (lowes		
				Left front		
	Right front					
S	Left rear					
<u> </u>	W	SD	W	Right rear		
	and blemishes may not be	displayed in the diagra	ım	Spare		
Body Inspecti	on Comments			Suspension		
				Suspension		
				Steering per		
				Shock absort		
	ring Body Inspection		Dry	Air Conditio		
Under Carriag	e and Under Bonnet	Inspection Comm	nents	Operation		
				Electrical / A		
				Head lights		
				Tail lights		
Interior Comm	nents			Indicators		
Seats:	Good			Dashboard v		
Carpets:	Good			Wipers (front		
Panels:		Window win				
Dashboard:	Window win					
General Comr	Window win					
				Window win		
				Rear view mi		
				Radio (basic		
Road Condition	ns During Test Drive	Dry		CD (basic tes		
Engine Timing Mechanism Timing Chain		Number of k				

		Requires	
Engino	OK	Attention	N/A
Engine			1
Oil level	<i>\</i>		
Smoke & fumes	V		
Engine performance			
Noise	- 1		
Coolant condition	\(\tau \)		
Cooling performance	- 1		
Radiator / Hoses (visual)	•		
Transmission		l I	l I
Operation			
Noise	•		
Clutch			
CV joints			
Wheel bearings	•		
Brakes	. 1		
Performance	•		
Hand brake	onth C	tumos)	
Tyres (lowest observed tread d	eptn or		- F
Left front			5.5 mm
Right front			5.5 mm
Left rear			5.5 mm
Right rear			5.5 mm
Spare	Yes		
Suspension			
Suspension performance			
Steering performance Shock absorbers			
Air Conditioning / Heater	1	Γ	
Operation Electrical / Accessories			
	•/		
Head lights	<i>V</i>		
Tail lights Indicators	•		
	V		
Dashboard warning lights	V		
Wipers (front & rear) Window winder FL	<i>V</i>		
Window winder FR Window winder FR			
	V		
Window winder RL	<i>V</i>		
Window winder RR	-		
Rear view mirrors	<i>\</i>		<u> </u>
Radio (basic test only)	•		
CD (basic test only)	2		
Number of keys		1	
Central locking	V		
Remote locking	<i>-</i>		
Sat. nav. (basic test only)	.1		
Reversing camera	•		

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 13 Nov 2025

Yuki Itohara

Glen Charlton

Yes

No

SIGNATURE

Kms