


Make:	Hyundai	Model:	Kona
Body Style:	SUV	Year:	2020
Rego No.:	MUP585	Rego Expiry:	11 Feb 2026
WoF Expiry:	12 Aug 2026	Odometer:	72,233 Kms
Good No.:	26049551	VIN:	KMHK281GULU096954
Next Service:	82,142km's	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



A number of small dents across roof panel, hail damage. Light scratches in left front headlight lens.

Under Carriage and Under Bonnet Inspection Comments

Seats:	Good
Carpets:	Good
Panels:	Average
Dashboard:	Good

Right side interior boot panel is cracked & broken, has parcel tray clip broken off it.

I have read and understood
this condition guide:

NAME _____

SIGNATURE

	OK	Requires Attention	N/A
Engine			
Oil level			✓
Smoke & fumes			✓
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			2.5 mm
Right front			4 mm
Left rear			7 mm
Right rear			7.5 mm
Spare	N/A		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		