

•	Report ID:	26,049,598	Version:	2
	Created:	26 Nov 2025		

	nuer	S Basi	C Condition Guide	Created: 26 Nov 2025				
Make:	Mazda	Model:	Bt-50			Requires		
Body Style:	Utility	Year:	2018	Engine	OK	Attention	N/A	
Rego No.:	LGC379	Rego Expiry:	11 Mar 2026	Oil level	· /			
WoF Expiry:	08 Dec 2026	Odometer:	294,388 Kms	Smoke & fumes	1			
Good No.:	26049598	VIN:	MM0UR0YG100803639		V		-	
Next Service:	301,000kms	Service History:	No	Engine performance Noise	1		-	
Note: This report is not a warranty			Coolant condition	1				
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or liagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a					1			
ull mechanical inspection prior to purchase and this can be arranged for an additional charge.			Cooling performance	-				
Кеу				Radiator / Hoses (visual)	<i>'</i>			
	= Rust $C = C$		3	Transmission		I	1	
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips			Operation					
	S S	SP S	SS	Noise	-			
				Clutch			-	
			CV joints	/				
s sc /		Wheel bearings						
- N				Brakes				
PT SC S S PT S S S PT			Performance	/				
			Hand brake					
			Tyres (lowest observed tread depth of tyres)					
			Left front		7	7.5 mr		
			Right front	8.0 mr				
			Left rear		4	4.0 mr		
			Right rear		2	4.0 mr		
Note: some defects a	and blemishes may not be displayed in the diagram			Spare	Yes	Yes		
Body Inspection	on Comments		Suspension					
Small stone cra	ck in middle of windso	creen. Two small de	ents in right front sill & small pin	Suspension performance	V			
	sill. High stop light in	top of rear canopy	door has a crack around light	Steering performance	V			
mounting.				Shock absorbers	V			
Conditions Dur	ing Body Inspection		Dry	Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments				Operation	V			
		<u> </u>		Electrical / Accessories		1		
				Head lights	V	I		
				Tail lights				
Interior Comm	nents	Indicators						

Interior Comm	Interior Comments	
Seats:	Good	
Carpets:	Good	
Panels:	Average	
Dashboard:	Good	
General Comments		

Catch on centre console lid is broken.

Road Condition	s During Test Drive	Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jason Young	
Published by:	Glen Charlton	
Inspection Date:	21 Nov 2025	

I have read and understood		
this condition guide:	NAME	SIGNATURE

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

1

1

1 1

2

1

1