

Basic Condition Guide

Report ID:	26,049,607	Version:	3
Created:	25 Nov 2025		

Operation Noise Clutch

CV joints Wheel bearings

Brakes Performance Hand brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights

Tail lights Indicators

Suspension performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Radio (basic test only) CD (basic test only)

Rear view mirrors

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

Steering performance Shock absorbers

Spare

ОК

1

1 1

1

Yes

J

1

1

J

1

J

1

1

1

1

1

1

Tyres (lowest observed tread depth of tyres)

Requires

Attention

N/A

6.0 mm

5.5 mm

4.0 mm

4.0 mm

				Created:	25 NOV 202
			_		
Make:	Ford	Model:	Ranger		
Body Style:	Utility	Year:	2021	Engine	
Rego No.: NUL521 WoF Expiry: 19 Nov 2026 Good No.: 26049607 Next Service: 215,000kms		Rego Expiry:	27 Apr 2026 Oil lev 200,141 Kms Smok		
		Odometer:			ımes
		VIN:	MNAUMFF50MW180827	Engine performance	
		Service History:	No	Noise	Tormanee
	Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or				
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					erformance
Key				Radiator /	Hoses (visual)
•	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmiss	ion
			3		

D = Dent	PT = Paint defect	P = Pin dent	SC = Stone C	hips	
SC (SP	S SC		S SC
SCSCW					SDW
S SC	E				SDP
SSC		SP	S		S SC

Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left front spot light blank missing out of front bumper. Alloy plates fitted to front bumper & rear tailgate.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Phone kit fitted to right side of dashboard. Reversing camera is not showing a very clear picture.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jason Young	
Published by:	Glen Charlton	
Inspection Date:	21 Nov 2025	

I have read and understood		
this condition guide:	NAME	SIGNATURE