

Report ID:	26,049,816	Version:	2
Created:	02 Dec 2025		


Make:	Mazda	Model:	CX-5
Body Style:	SUV	Year:	2021
Rego No.:	NSQ189	Rego Expiry:	22 Mar 2026
WoF Expiry:	21 Sep 2026	Odometer:	148,120 Kms
Good No.:	26049816	VIN:	JM0KF4WLA00697564
Next Service:	156,000km's	Service History:	Yes

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Small stone crack in middle bottom area of windscreen. Damage to left front headlight

Conditions During Body Inspection	Wet	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comm	ents
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

# **General Comments**

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jason Young	
Published by:	Jason Young	
Inspection Date:	02 Dec 2025	

I have read	and	understood
thic condition	on a	uido

NAME			

	ОК	Requires Attention	N/A
Engine	<u> </u>	7 teterreiori	14//
Oil level	<b>/</b>		
Smoke & fumes	<b>/</b>		
Engine performance	/		
Noise	\( \text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tin}\text{\tin}\text{\ti}}\\ \tittt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\texi}\text{\text{\texi}\text{\text{\text{\texi}\text{\text{\texi}\text{\text{\texi}\text{\text{\texi}\text{\texi}\text{\texi}\text{\texi}\text{\texi}\tilint{\text{\texit{\text{\texi}\texit{\texi{\texi{\tex		
Coolant condition	<b>/</b>		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	<b>✓</b>		
Noise	/		
Clutch			~
CV joints	<b>/</b>		
Wheel bearings	/		
Brakes			
Performance	<b>/</b>		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			6 mm
Right front			6 mm
Left rear			6 mm
Right rear			6 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	<b>/</b>		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	<b>✓</b>		
Electrical / Accessories			
Head lights	/		
Tail lights	<b>V</b>		
Indicators	/		
Dashboard warning lights	V V V		
Wipers (front & rear)	~		
Window winder FL	/		
Window winder FR	<b>V</b>		
Window winder RL			
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	<b>/</b>		
CD (basic test only)			1
Number of keys	2	-	
Central locking	/		
Remote locking	<b>✓</b>		
Sat. nav. (basic test only)	/		
Reversing camera	<b>/</b>		

SIGNATURE		