


Basic Condition Guide

•	Report ID:	26,049,859	Version:	1
	Created:	02 Dec 2025		

Make:	Mitsubishi	Model:	Triton			
Body Style:	Utility	Year:	2021			
Rego No.:	NHZ8	Rego Expiry:	09 Feb 2026			
WoF Expiry:	14 Mar 2026	Odometer:	276,336 Kms			
Good No.:	26049859	VIN:	MMAJLKL10MH004720			
Next Service:	276,280km's	Service History:	Yes			
Note: This report is not a warranty						
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a						

full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Both right & left side running boards are dented & have cracks in end caps. Both rear taillight lenses are cracked & broken. Small stone crack in left side of windscreen.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments		
Seats:	Average	
Carpets:	Good	
Panels:	Average	
Dashboard:	Good	

General Comments

Drivers door frame seal is damaged & torn. Small hole in fabric on base pad of driver's seat.

Road Conditions During Test Drive		s During Test Drive	Dry
Engine Timing Mechanism		Иеchanism	Timing Chain
	Evidence of Cam Belt Replacement		Yes No Kms
	Inspected by:	Jason Young	
	Published by:	Jason Young	
	Inspection Date:	02 Dec 2025	

have read and understood			
this condition guide:	NAME		

Engine Oil level Smoke & fumes	
Smoke & fumes	
	_
Engine performance	
Engine performance V Noise V	
Coolant condition Cooling performance	
Cooling performance	
Radiator / Hoses (visual)	
Transmission	
Operation 🗸	
Noise 🗸	
Clutch	<u>′</u>
CV joints	
Wheel bearings 🗸	
Brakes	
Performance 🗸	
Hand brake	
Tyres (lowest observed tread depth of tyres)	
Left front 8 r	nm
Right front 8 r	nm
Left rear 5.5 r	nm
Right rear 5.5 r	nm
Spare Yes	
Suspension	
Suspension performance 🗸	
Steering performance 🗸	
Shock absorbers 🗸	
Air Conditioning / Heater	
Operation 🗸	
Electrical / Accessories	
Head lights 🗸	
Tail lights 🗸	
Indicators 🗸	
Dashboard warning lights	
Wipers (front & rear) Window winder FL	
Window winder FL 🗸	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	_
Number of keys 1	
Central locking 🗸	
Remote locking 🗸	
Sat. nav. (basic test only)	_
Reversing camera 🗸	_

SIGNATURE			