

on Guide

•	Report ID: 26,050,047		Version:	3
	Created:	19 Dec 2025		

ger			Requires		
<u> </u>	Fundan	OK	Attention	N/A	
an 2026	Engine				
096 Kms	Oil level	/			
UMFF60MW191651	Smoke & fumes	/			
	Engine performance	/			
	Noise	/			
not been dismantled or	Coolant condition	V			
old. The Vendor recommends a ditional charge.	Cooling performance	/			
	Radiator / Hoses (visual)	/			
W = Significant scuffs	Transmission				
OS	Operation	/			
SD	Noise	V			
30	Clutch			1	
S	CV joints	V			
	Wheel bearings	1			
	Brakes				
	Performance	V			
S D SC	Hand brake	1			
	Tyres (lowest observed tread depth of tyres)				
	Left front 8.0 mm				
SD	Right front		8.0 mm		
	Left rear	8.0 mm			
SP		Right rear 8.0 mm			
	Spare	Yes		.0 11111	
	Suspension	163			
ey is missing. Both sill	-		T		
y is missing. Dour sin	Suspension performance	/			
	Steering performance				
	Shock absorbers	/			
	Air Conditioning / Heater				
	Operation	/			
	Electrical / Accessories			1	
	Head lights	/			
	Tail lights	/			
	Indicators	V			
	Dashboard warning lights	/			
	Wipers (front & rear)	/			
	Window winder FL	/			
	Window winder FR	V			
	Window winder RL	/			
	Window winder RR	1			
	Rear view mirrors	1			
	Radio (basic test only)	1			
	CD (basic test only)			1	
	Number of keys	2	1		
Kms	Central locking	1			
5	Remote locking	1			
	Sat. nav. (basic test only)	1			
	Jack Have (Dasie test Offiy)		1	I	

Turners	
----------------	--


Basic	Conditio
Dasio	Cornaitie

Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2022
Rego No.:	PAD381	Rego Expiry:	18 Jan 2026
WoF Expiry:	24 Jan 2026	Odometer:	150,096 Kms
Good No.:	26050047	VIN:	MNAUMFF60MW191651
Nevt Service	160 000kms	Service History	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have diagnostic testing undertaken. The vehicle has been driven up to 50km/h from co full mechanical inspection prior to purchase and this can be arranged for an add

Key						
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs		
D – Dent	PT - Paint defect	P — Pin dent	SC - Stone Chins			



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Right side rear bumper step plate clips are broken. Canopy ke front step area paint is worn.

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments			
Seats: Side of right front base pad is worn,torn.			
Carpets: Good			
Panels:	Good		
Dashboard: Good			
General Comments			

Road Conditions During Test Drive Dry Cambelt **Engine Timing Mechanism ✓** No Evidence of Cam Belt Replacement Yes Yuki Itohara Inspected by: Published by: Glen Charlton Inspection Date: 11 Dec 2025

I have	read	and	understo	ood
this co	nditi	on a	uide	

NAME			

Reversing camera