

Basic Condition Guide

•	Report ID:	26,050,132	Version:	1
	Created:	16 Dec 2025		

Engine

Oil level
Smoke & fumes
Engine performance

Noise

Coolant condition

Transmission
Operation
Noise

Wheel bearings

Clutch CV joints

Brakes
Performance

Hand brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)
Window winder FL
Window winder FR

Window winder RL

Window winder RR

Radio (basic test only)

CD (basic test only)

Number of keys
Central locking
Remote locking

Rear view mirrors

Steering performance

Shock absorbers

Operation

Head lights

Tail lights
Indicators

Spare

Tyres (lowest observed tread depth of tyres)

Cooling performance

Radiator / Hoses (visual)

ОК

1

1

Yes

J

1

J

J

1

V

1

1

Requires

Attention

N/A

10.0 mm

10.0 mm

9.5 mm

9.5 mm


Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2021
Rego No.:	NYJ148	Rego Expiry:	12 Jun 2026
WoF Expiry:	17 Dec 2025	Odometer:	188,356 Kms
Good No.:	26050132	VIN:	MNAUMFF50MW186506
Next Service:	193,300kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

ite y				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Three small stone cracks in left side of windscreen, two of them are a double hit & are not repairable. Alloy brackets fitted to front bumper & rear tailgate. Plastic trim on bottom of rear canopy door is broken & has been taped in place.

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Interior Comments	
Seats:	Average
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

I have read and understood this condition guide:

Hole in fabric on base pad of driver's seat. Keys for both right & left side locks on rear canopy door are not working. Phone kit fitted to right side of dashboard & phone aerial fitted to left front guard.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Can	n Belt Replacement	Yes No Kms
Inspected by:	Jason Young	
Published by:	Glen Charlton	
Inspection Date:	16 Dec 2025	

J		1	l
Sat. nav. (basic test only)			1
Reversing camera	/		
SIGNATURE			