

# **Basic Condition Guide**

| • | Report ID: | 26,050,184  | Version: | 1 |
|---|------------|-------------|----------|---|
|   | Created:   | 17 Dec 2025 |          |   |

Requires


| Make:         | LDV         | Model:           | V80               |
|---------------|-------------|------------------|-------------------|
| Body Style:   | Van         | Year:            | 2019              |
| Rego No.:     | MPT964      | Rego Expiry:     | 19 Mar 2026       |
| WoF Expiry:   | 17 Dec 2026 | Odometer:        | 204,175 Kms       |
| Good No.:     | 26050184    | VIN:             | LSKG5GL15KA084773 |
| Next Service: | 202,100kms  | Service History: | No                |

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

#### Kev

| Key         |                   |              |                  |                        |
|-------------|-------------------|--------------|------------------|------------------------|
| S = Scratch | R = Rust          | C = Crack    | * = Decals       | W = Significant scuffs |
| D = Dent    | PT = Paint defect | P = Pin dent | SC = Stone Chips |                        |



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Service is overdue. Right shill front step area paint is worn.

| Conditions During Body Inspection                   | Dry |  |  |
|---|-----|--|--|
| Under Carriage and Under Bonnet Inspection Comments |     |  |  |

| Interior Comments |                                  |  |
|-------------------|----------------------------------|--|
| Seats:            | Good                             |  |
| Carpets:          | Right front carpet is worn,torn. |  |
| Panels:           | Good                             |  |
| Dashboard:        | Good                             |  |

### **General Comments**

Left rear door lock regulator is faulty, also not smooth to open. AC is not cold. Right front door lock knob is missing.

| Road Conditions During Test Drive |               | Dry     |             |     |
|-----------------------------------|---------------|---------|-------------|-----|
| Engine Timing Mechanism           |               | Cambelt |             |     |
| Evidence of Cam Belt Replacement  |               | Yes     | <b>✓</b> No | Kms |
| Inspected by:                     | Yuki Itohara  |         |             |     |
| Published by:                     | Glen Charlton |         |             |     |
| Inspection Date:                  | 16 Dec 2025   |         |             |     |

| I have read and understood |
|----------------------------|
| this condition guide:      |

| NAME |  |
|------|--|
|      |  |

|                                | OK       | Attention | N/A      |
|--------------------------------|----------|-----------|----------|
| Engine                         |          |           |          |
| Oil level                      | <b>✓</b> |           |          |
| Smoke & fumes                  | <b>/</b> |           |          |
| Engine performance             | V<br>V   |           |          |
| Noise                          | <b>/</b> |           |          |
| Coolant condition              | ~        |           |          |
| Cooling performance            | ~        |           |          |
| Radiator / Hoses (visual)      | ~        |           |          |
| Transmission                   |          |           |          |
| Operation                      | <b>/</b> |           |          |
| Noise                          | <b>/</b> |           |          |
| Clutch                         |          |           | 1        |
| CV joints                      | <b>✓</b> |           |          |
| Wheel bearings                 | <b>/</b> |           |          |
| Brakes                         |          |           |          |
| Performance                    |          |           |          |
| Hand brake                     |          |           |          |
| Tyres (lowest observed tread d | enth of  | tures)    |          |
| Left front                     | Сригог   |           | ).0 mm   |
|                                |          |           |          |
| Right front                    |          |           |          |
| Left rear                      |          |           | 6.5 mm   |
| Right rear                     |          |           | 6.0 mm   |
| Spare                          | Yes      |           |          |
| Suspension                     |          | Γ         |          |
| Suspension performance         | ✓<br>✓   |           |          |
| Steering performance           | <i>'</i> |           |          |
| Shock absorbers                |          |           |          |
| Air Conditioning / Heater      |          |           |          |
| Operation                      |          | <b>'</b>  |          |
| Electrical / Accessories       |          |           |          |
| Head lights                    | <b>/</b> |           |          |
| Tail lights                    | <b>/</b> |           |          |
| Indicators                     | <b>✓</b> |           |          |
| Dashboard warning lights       | /        |           |          |
| Wipers (front & rear)          | /        |           |          |
| Window winder FL               | /        |           |          |
| Window winder FR               | <b>/</b> |           |          |
| Window winder RL               |          |           | <b>'</b> |
| Window winder RR               |          |           | 1        |
| Rear view mirrors              | <b>✓</b> |           |          |
| Radio (basic test only)        | /        |           |          |
| CD (basic test only)           |          |           | 1        |
| Number of keys                 | 2        | ı         |          |
| Central locking                |          | ·         |          |
| Remote locking                 |          | ·         |          |
| Sat. nav. (basic test only)    |          |           |          |
| Reversing camera               |          |           | <u> </u> |
| neversing camera               |          |           |          |