


Make:	Toyota	Model:	Fortuner
Body Style:	SUV	Year:	2022
Rego No.:	PAK144	Rego Expiry:	07 Feb 2026
WoF Expiry:	29 Jan 2027	Odometer:	178,349 Kms
Good No.:	26050454	VIN:	MR0BA3FS401125224
Next Service:	180,000kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Both rear inner wheel arch has minor dents. Right sill paint is worn. Numbers of pin dents on right front and rear doors. Right front door seal rubber is torn. Small stone cracks in left side of windshield. Left tail light is cracked. Front grille is cracked. Left license light is not operating.

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**
**Interior Comments**

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

**General Comments**

1 of audio control knob is missing. 1 of switch blank cap is missing.  
 3 raw seat head rests are missing. 1 of key brake is missing. Noodling has stain and minor scratches.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Yuki Itohara
Published by:	Glen Charlton
Inspection Date:	07 Jan 2026

I have read and understood  
 this condition guide:

NAME \_\_\_\_\_

Report ID:	26,050,454	Version:	1
Created:	20 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	4.0	mm	
Right front	4.5	mm	
Left rear	4.0	mm	
Right rear	4.5	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights			✓
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

SIGNATURE \_\_\_\_\_