


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Mitsubishi  | Model:           | Triton            |
| Body Style:   | Utility     | Year:            | 2017              |
| Rego No.:     | KRQ905      | Rego Expiry:     | 26 Apr 2026       |
| WoF Expiry:   | 09 Aug 2026 | Odometer:        | 208,325 Kms       |
| Good No.:     | 26050533    | VIN:             | MMAJYKL10HH012969 |
| Next Service: | 222,000kms  | Service History: | Yes               |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Two small stone cracks in windscreen. Surface rust along top edge of windscreen. Large cracks, hole & scratches/scuff on left rear bumper cover. Dents in left & right rear corner panels of ute cab.

|                                   |     |
|-----------------------------------|-----|
| Conditions During Body Inspection | Wet |
|-----------------------------------|-----|

**Under Carriage and Under Bonnet Inspection Comments**
**Interior Comments**

|            |         |
|------------|---------|
| Seats:     | Average |
| Carpets:   | Good    |
| Panels:    | Average |
| Dashboard: | Good    |

**General Comments**

Large hole in fabric on base pad of driver's seat. Right rear interior door speaker grille has a crack in it.

|                                   |  |
|-----------------------------------|--|
| Road Conditions During Test Drive | Wet  |
| Engine Timing Mechanism           | Timing Chain   |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| Inspected by:                     | Jason Young  |
| Published by:                     | Jason Young  |
| Inspection Date:                  | 16 Jan 2026  |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 26,050,533  | Version: | 1 |
| Created:   | 16 Jan 2026 |          |   |

|   | OK | Requires Attention | N/A |
|---|----|--------------------|-----|
| <b>Engine</b>                                       |    |                    |     |
| Oil level   | ✓  |                    |     |
| Smoke & fumes                                       | ✓  |                    |     |
| Engine performance                                  | ✓  |                    |     |
| Noise   | ✓  |                    |     |
| Coolant condition                                   | ✓  |                    |     |
| Cooling performance                                 | ✓  |                    |     |
| Radiator / Hoses (visual)                           | ✓  |                    |     |
| <b>Transmission</b>                                 |    |                    |     |
| Operation   | ✓  |                    |     |
| Noise   | ✓  |                    |     |
| Clutch  |    |                    | ✓   |
| CV joints   | ✓  |                    |     |
| Wheel bearings                                      | ✓  |                    |     |
| <b>Brakes</b>                                       |    |                    |     |
| Performance   | ✓  |                    |     |
| Hand brake  | ✓  |                    |     |
| <b>Tyres (lowest observed tread depth of tyres)</b> |    |                    |     |
| Left front  |    | 9 mm               |     |
| Right front   |    | 10 mm              |     |
| Left rear   |    | 10 mm              |     |
| Right rear  |    | 10 mm              |     |
| Spare   |    | Yes                |     |
| <b>Suspension</b>                                   |    |                    |     |
| Suspension performance                              | ✓  |                    |     |
| Steering performance                                | ✓  |                    |     |
| Shock absorbers                                     | ✓  |                    |     |
| <b>Air Conditioning / Heater</b>                    |    |                    |     |
| Operation   | ✓  |                    |     |
| <b>Electrical / Accessories</b>                     |    |                    |     |
| Head lights   | ✓  |                    |     |
| Tail lights   | ✓  |                    |     |
| Indicators  | ✓  |                    |     |
| Dashboard warning lights                            | ✓  |                    |     |
| Wipers (front & rear)                               | ✓  |                    |     |
| Window winder FL                                    | ✓  |                    |     |
| Window winder FR                                    | ✓  |                    |     |
| Window winder RL                                    | ✓  |                    |     |
| Window winder RR                                    | ✓  |                    |     |
| Rear view mirrors                                   | ✓  |                    |     |
| Radio (basic test only)                             | ✓  |                    |     |
| CD (basic test only)                                | ✓  |                    |     |
| Number of keys                                      | 1  |                    |     |
| Central locking                                     | ✓  |                    |     |
| Remote locking                                      | ✓  |                    |     |
| Sat. nav. (basic test only)                         |    |                    | ✓   |
| Reversing camera                                    | ✓  |                    |     |

SIGNATURE \_\_\_\_\_