

Report ID:	26,050,735	Version:	1
Created:	30 Jan 2026		


Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2014
Rego No.:	HQS146	Rego Expiry:	16 Nov 2026
WoF Expiry:	12 Sep 2026	Odometer:	281,881 Kms
Good No.:	26050735	VIN:	MNAUM2F50EW281296
Next Service:	294,572km's	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Overspray paint all over steel deck & rear panel on ute cab. Both front spot light blanks are missing. Front grille is broken. Both rear wheel centre caps are missing. Not jack or tools with vehicle. Large crack along bottom left side of windscreen. Also small stone crack in right side of screen.

Conditions During Body Inspection: Wet Dry

Under Carriage and Under Bonnet Inspection Comments

Crack & hole in right side wing mirror cover. GPS dome fitted to roof panel. Driver's door check strap is cracked.

Interior Comments

Seats:	Average
Carpets:	Good
Panels:	Average
Dashboard:	Average

General Comments

Has paint on some of interior panels in vehicle. Screw holes in centre console & dashboard. Trim on inside floor area of right front door needs refitted. Left side interior roof grab handle is broken off & missing. Catch broken on centre console lid. Driver's door frame seal is damaged & torn.

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Jason Young	
Published by:	Glen Charlton	
Inspection Date:	29 Jan 2026	

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5.0 mm
Right front			5.0 mm
Left rear			4.0 mm
Right rear			5.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____