

Report ID:	26,050,742	Version:	7
Created:	04 Mar 2026		


Make:	Hyundai	Model:	Santa FE
Body Style:	SUV	Year:	2011
Rego No.:	GCL479	Rego Expiry:	25 Mar 2026
WoF Expiry:	30 Sep 2026	Odometer:	199,071 Kms
Good No.:	26050742	VIN:	KMHS81XSCU813043
Next Service:	199,600kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left side of front bumper fitting is broken. Rear bumper valance is not fitted correctly. Large dents on roof. Left front inner guard liner is broken and missing front part.

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Side of right front base pad is worn.
Carpets:	Good
Panels:	Small rip around right front door handle.
Dashboard:	Good

General Comments

Cargo area floor board (Tool storage) opener is broken. Rear foglight is not operating. Left rear seat folding up side lever is faulty, rear lever is working. Has drive line shudder. Rear left window can not be operated from main switch.

Road Conditions During Test Drive Dry

Engine Timing Mechanism Timing Chain

Evidence of Cam Belt Replacement Yes No Kms

Inspected by: Yuki Itohara

Published by: Glen Charlton

Inspection Date: 04 Mar 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5.5 mm
Right front			6.0 mm
Left rear			6.5 mm
Right rear			7.5 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____