


Make:	MG	Model:	HS
Body Style:	SUV	Year:	2021
Rego No.:	NTW228	Rego Expiry:	17 Apr 2026
WoF Expiry:	24 Nov 2026	Odometer:	185,531 Kms
Good No.:	26050788	VIN:	LSJA24391MN110286
Next Service:	198,270km's	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Small stone crack in left side of windscreen.

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Average
Carpets:	Good
Panels:	Average
Dashboard:	Good

General Comments

Intermittent knock in steering column when turning steering wheel. Leather on base pad of driver's seat is damaged & cracking. Covering on centre console lid is starting to come off front bottom edge, needs refitted.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Jason Young
Published by:	Glen Charlton
Inspection Date:	02 Feb 2026

I have read and understood
this condition guide:

NAME _____

Report ID:	26,050,788	Version:	1
Created:	02 Feb 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	6.0	mm	
Right front	6.0	mm	
Left rear	6.5	mm	
Right rear	6.5	mm	
Spare	N/A		
Suspension			
Suspension performance	✓		
Steering performance			✓
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

SIGNATURE _____