

# **Basic Condition Guide**

Report ID:	26,053,238	Version:	1
Created:	05 Nov 2025		


Make:	Mazda	Model:	CX-8
Body Style:	suv	Year:	2020
Rego No.:	NCS562	Rego Expiry:	22 Apr 2026
WoF Expiry:	06 Dec 2025	Odometer:	116,514 Kms
Good No.:	26053238	VIN:	JM0KG4W2A00302768
Next Service:	118,000 kms	Service History:	No

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

#### Kev

Rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Windscreen stone chip cracked

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

### 4wd

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	LF door trim scratches	
Dashboard:	Good	
General Comments		

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Vasanthakumar Mayilswamy		
Published by:	Vasanthakumar Mayilswamy		
Inspection Date:	05 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	<b>/</b>		
Smoke & fumes	<b>/</b>		
Engine performance	\( \text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\tin}\exitit{\text{\ti}\text{\tinit}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\tinit}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\}\tittitt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\tittileft{\text{\tinit}\xi}\\\ \tittith}\\ \tittt{\text{\text{\text{\text{\ti}\tittileft{\text{\text{\text{\texi{\texi{\texi}\tii}\\ \tittt{\tititt{\text{\texit{\text{\texi}\tint{\text{\tii}}\texi		
Noise	<b>/</b>		
Coolant condition	<b>/</b>		
Cooling performance	<b>/</b>		
Radiator / Hoses (visual)	<b>/</b>		
Transmission		l	
Operation	<b>V</b>		
Noise	<b>/</b>		
Clutch			1
CV joints	<b>/</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance	/		
Hand brake			
Tyres (lowest observed tread d	epth of	L tvres)	
Left front			5.5 mm
Right front			5.5 mm
Left rear			5.5 mm
Right rear			5.5 mm
Spare	Yes		
Suspension			
Suspension performance			
Steering performance	· /		
Shock absorbers			
Air Conditioning / Heater	•		
Operation			
Electrical / Accessories	•		
Head lights			
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR			
Window winder RL			
Window winder RR			
Rear view mirrors			
Radio (basic test only)	~		
CD (basic test only)	•		
Number of keys	2	I	
Central locking	4		
Remote locking	_	I	I
Sat. nav. (basic test only) Reversing camera	<i>V</i>		

I have read and understood this condition guide:

NAME

SIGNATURE