

## **Basic Condition Guide**

| Report ID: | 26,054,382  | Version: | 1 |
|------------|-------------|----------|---|
| Created:   | 04 Dec 2025 |          |   |

|                                  | Ulliel   |                           |                           | Created: 04 Dec 2025         |          |           |          |
|----------------------------------|--|---------------------------|---------------------------|------------------------------|----------|-----------|----------|
| Make:                            | Toyota   | Model:                    | Aqua                      |                              |          | Requires  |          |
| Body Style:                      | Hatchback  | Year:                     | 2015                      | -                            | OK       | Attention | N/A      |
| Rego No.:                        | PHF328   | Rego Expiry:              | 30 Nov 2025               | Engine                       |          |           |          |
| WoF Expiry:                      | 10 Jan 2026  | Odometer:                 | 208,495 Kms               | Oil level                    | /        |           |          |
| Good No.:                        | 26054382   | VIN:                      | 7AT0H65YX22391380         | Smoke & fumes                | <i>'</i> |           | -        |
| Next Service:                    | 211,276 kms  | Service History:          | No                        | Engine performance           | V        |           |          |
| ote: This report is              | ·  | ,                         | Noise                     | V                            |          |           |          |
| is report is a guide             | only. Consideration is madertaken. The vehicle has | de for age and mileage. P | Coolant condition         | V                            |          | <u> </u>  |          |
| Il mechanical inspe              | ection prior to purchase a                         | nd this can be arranged f | Cooling performance       | V                            |          | -         |          |
| <b>е</b> у                       |  |                           | Radiator / Hoses (visual) | /                            |          |           |          |
|                                  |  | Crack *= Deca             | Transmission              |                              |          |           |          |
| = Dent P                         | T = Paint defect P = I                             | Pin dent SC = Sto         | ne Chips                  | Operation                    | -        |           | <u> </u> |
| S                                | W  | SP SP                     | W (                       | Noise                        | -        |           |          |
|                                  |  |                           |                           | Clutch                       |          |           | -        |
|                                  | $\sim$   |                           | S                         | CV joints                    | <b>/</b> |           | <u> </u> |
| SDC                              |  |                           |                           | Wheel bearings               | <b>/</b> |           |          |
| $\neg \neg P$                    | 18   |                           |                           | Brakes                       |          |           |          |
| 1                                |  |                           |                           | Performance                  | -        |           |          |
|                                  |  |                           |                           | Hand brake                   | <b>/</b> |           |          |
| SD                               |  |                           | NL HA                     | Tyres (lowest observed tread | depth of | tyres)    |          |
|                                  |  |                           | S                         | Left front                   |          |           | 5 m      |
|                                  |  |                           |                           | Right front                  |          |           | 5 m      |
|                                  | 14/  |                           | Left rear                 | 4 mr                         |          |           |          |
| P                                | W  | S D P                     | Right rear                |                              |          | 5 mi      |          |
| ote: some defects                | and blemishes may not b                            | e displayed in the diagra | Spare                     | Yes                          |          |           |          |
|                                  | on Comments  |                           |                           | Suspension                   |          | 1         |          |
| Vindscreen sto<br>L headlight sc | ne chip cracked                                    |                           |                           | Suspension performance       | V        |           |          |
| L ricadiigiit 30                 | idionod  |                           |                           | Steering performance         | V        |           |          |
|                                  |  |                           | T                         | Shock absorbers              | V        |           | <u> </u> |
| Conditions Dur                   | ring Body Inspection                               |                           | Air Conditioning / Heater |                              |          |           |          |
| Under Carriag                    | je and Under Bonne                                 | t Inspection Comm         | nents                     | Operation                    | <b>/</b> |           |          |
| wd                               |  |                           |                           | Electrical / Accessories     |          |           |          |
|                                  |  |                           |                           | Head lights                  | <b>/</b> |           |          |
|                                  |  |                           |                           | Tail lights                  | <b>/</b> |           |          |
| nterior Comm                     | nents  |                           |                           | Indicators                   | <b>/</b> |           |          |
| Seats:                           | Good   |                           |                           | Dashboard warning lights     | V        |           | <u> </u> |
| Carpets:                         | Good   |                           |                           | Wipers (front & rear)        | <b>/</b> |           |          |
| Panels:                          | Good   |                           |                           | Window winder FL             | /        |           |          |
| Dashboard:                       | Good   |                           | Window winder FR          | <b>/</b>                     |          |           |          |
| General Comr                     | ments  |                           |                           | Window winder RL             | <b>/</b> |           |          |
|                                  |  |                           |                           | Window winder RR             | V        |           |          |
|                                  |  |                           |                           | Rear view mirrors            | V        |           |          |
|                                  |  |                           |                           | Radio (basic test only)      | /        |           |          |
| Road Condition                   | ns During Test Drive                               | Dry                       | CD (basic test only)      | ~                            |          |           |          |
| Engine Timing                    | Mechanism  | Timing Chain              | Number of keys            | 1                            |          |           |          |
| Evidence of Ca                   | m Belt Replacement                                 | Yes                       | No Kms                    | Central locking              | 1        |           |          |
| Inspected by:                    | Vasanthakumar                                      | <br>Mayilswamy            |                           | Remote locking               | 1        |           |          |
| Published by:                    | Vasanthakumar I                                    |                           |                           | Sat. nav. (basic test only)  |          |           | ~        |
| 1                                |  |                           |                           |                              |          |           | _        |

I have read and understood this condition guide:

Inspection Date: 04 Dec 2025

NAME

SIGNATURE

Reversing camera