

## **Basic Condition Guide**

| • | Report ID: 26,054,459 |             | Version: | 1 |
|---|-----------------------|-------------|----------|---|
|   | Created:              | 03 Dec 2025 |          |   |


|  | ОК       | Requires<br>Attention | N/A  |
|--|----------|-----------------------|------|
| Engine                                     |          |                       |      |
| Oil level                                  | /        |                       |      |
| Smoke & fumes                              | <b>/</b> |                       |      |
| Engine performance                         | <b>/</b> |                       |      |
| Noise                                      | <b>/</b> |                       |      |
| Coolant condition                          | /        |                       |      |
| Cooling performance                        | <b>/</b> |                       |      |
| Radiator / Hoses (visual)                  | <b>/</b> |                       |      |
| Transmission                               |          |                       |      |
| Operation                                  | <b>'</b> |                       |      |
| Noise                                      | <b>/</b> |                       |      |
| Clutch                                     |          |                       | 1    |
| CV joints                                  | /        |                       |      |
| Wheel bearings                             | /        |                       |      |
| Brakes                                     |          |                       |      |
| Performance                                | /        |                       |      |
| Hand brake                                 | /        |                       |      |
| Tyres (lowest observed tread de            | epth of  | tyres)                |      |
| Left front                                 |          |                       | 6 mm |
| Right front                                |          |                       | 3 mm |
| Left rear                                  |          |                       | 3 mm |
| Right rear                                 |          |                       | 3 mm |
| Spare                                      | N/A      |                       |      |
| Suspension                                 |          |                       |      |
| Suspension performance                     | <b>'</b> |                       |      |
| Steering performance                       | <b>/</b> |                       |      |
| Shock absorbers                            | <b>/</b> |                       |      |
| Air Conditioning / Heater                  |          |                       |      |
| Operation                                  | <b>/</b> |                       |      |
| Electrical / Accessories                   |          |                       |      |
| Head lights                                | /        |                       |      |
| Tail lights                                | <b>/</b> |                       |      |
| Indicators                                 | <b>/</b> |                       |      |
| Dashboard warning lights                   | 1        |                       |      |
| Wipers (front & rear)                      | <b>/</b> |                       |      |
| Window winder FL                           | /        |                       |      |
| Window winder FR                           | <b>/</b> |                       |      |
| Window winder RL                           | <b>/</b> |                       |      |
| Window winder RR                           | •        |                       |      |
| Rear view mirrors                          | •        |                       |      |
| Radio (basic test only)                    | /        |                       |      |
| CD (basic test only)                       | <b>/</b> |                       |      |
| Number of keys                             | 1        |                       |      |
| Central locking                            | •        |                       |      |
|  |          |                       |      |
| Remote locking                             |          |                       |      |
| Remote locking Sat. nav. (basic test only) |          |                       |      |

| Make:              | Toyota      | Model:           | Aqua              |
|--------------------|-------------|------------------|-------------------|
| Body Style:        | Hatchback   | Year:            | 2017              |
| Rego No.:          | PRT635      | Rego Expiry:     | 30 Jan 2026       |
| WoF Expiry:        | 18 Mar 2026 | Odometer:        | 188,546 Kms       |
| Good No.: 26054459 |             | VIN:             | 7AT0H65YX23688851 |
| Next Service:      | 194,585 kms | Service History: | No                |

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

\* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

L sill dent and scratches Tyre mobility kit available

| Conditions During Body Inspection                   | Wet |  |  |  |
|---|-----|--|--|--|
| Under Carriage and Under Bonnet Inspection Comments |     |  |  |  |

Fwd

| Interior Comments |                     |  |  |  |
|-------------------|---------------------|--|--|--|
| Seats:            | Good                |  |  |  |
| Carpets:          | Good                |  |  |  |
| Panels:           | Boot trim scratches |  |  |  |
| Dashboard:        | Good                |  |  |  |
| General Comments  |                     |  |  |  |

| Road Conditions During Test Drive |  | Wet          |  |
|-----------------------------------|--|--------------|--|
| Engine Timing Mechanism           |  | Timing Chain |  |
| Evidence of Cam Belt Replacement  |  | Yes No Kms   |  |
| Inspected by:                     | Inspected by: Vasanthakumar Mayilswamy |              |  |
| Published by:                     | Vasanthakumar Mayilswamy               |              |  |
| Inspection Date:                  | 03 Dec 2025                            |              |  |

| I have  | read  | and  | understo | ood |
|---------|-------|------|----------|-----|
| this co | nditi | on a | uide     |     |

| NAME |  |  |
|------|--|--|