

•	Report ID:	26,057,294	Version:	2
	Created:	17 Nov 2025		

		Rasi	c Condition Guide	Report ID:	26,057,294	Vei	rsion: 2	
	urner			Created:	17 Nov 2025			
Make:	Mitsubishi	Model:	Outlander	_			Requires	
Body Style:	SUV	Year:	2022			OK	Attention	N/A
Rego No.:	PAD953	Rego Expiry:	10 Feb 2026	Engine				1
WoF Expiry:	21 Mar 2026	Odometer:	78,558 Kms	Oil level		<i>'</i>		-
Good No.:	26057294	VIN:	JMFXTGF8WLZ028989	Smoke & fu		/		-
Next Service:	86000	Service History:	Yes	Engine performance			-	
Note: This report is not a warranty				Noise Coolant condition		V		-
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or					Cooling performance			-
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Radiator / Hoses (visual)		<i>'</i>		-
Кеу								
	R=Rust C=C			Transmission				
D = Dent I	PT = Paint defect P = P	Fin dent $SC = Sto$	ne Chips	Operation		/		-
		P		Noise		/		
				Clutch				/
	(0)=		S	CV joints		/		-
				Wheel bearings				
				Performance			I	_
SC SC						/		<u> </u>
				Hand brake				
SC P				Tyres (lowest observed tread depth of tyres)				
				Left front				4.0 m
				Right front		5.0 m		
				Left rear		2.0 n		
P				Right rear		3.0 m		
	s and blemishes may not be	e displayed in the diagra	ım .	Spare		Yes		
Body Inspect	tion Comments			Suspensio			ı	
					performance	/		<u> </u>
				Steering pe		/		<u> </u>
				Shock abso		/		
Conditions During Body Inspection Dry				Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments				Operation		/		
2Wheel drive.				Electrical /	Accessories		,	
				Head lights	;	/		
			Tail lights		/		<u> </u>	
Interior Comments			Indicators		/		<u> </u>	
Seats:	Good			Dashboard	warning lights	s 🗸		
Carpets:	Good			Wipers (fro	nt & rear)	& rear)		
Panels:	Good			Window wi	inder FL	/		
Dashboard: Good			Window wi	inder FR	/			
General Comments				Window wi	inder RL	/		

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Rajesh Mayan	
Published by:	Ben Nicholson	
Inspection Date:	31 Oct 2025	

I have read and understood
this condition guide:

NAME			

SIGNATURE			

•

2

1

•

Window winder RR Rear view mirrors

Radio (basic test only) CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera