

Basic Condition Guide

•	Report ID:	26,057,605	Version:	2
	Created:	20 Nov 2025		

(-5		011	Requires	N1/A
21	Engine	OK	Attention	N/A
Dec 2025	Engine			
,821 Kms	Oil level	/		
I0KF2W7A00704629	Smoke & fumes			
S	Engine performance	/		
	Noise	/		
ave not been dismantled or	Coolant condition	/		
n cold. The Vendor recommends a additional charge.	Cooling performance	/		
	Radiator / Hoses (visual)			
W = Significant scuffs	Transmission			
hips	Operation	/		
SD	Noise	/		
	Clutch			✓
	CV joints	/		
	Wheel bearings	/		
	Brakes			
	Performance	V		
	Hand brake	/		
	Tyres (lowest observed tread	depth of	tyres)	
	Left front		<u> </u>	5 mn
D	Right front			5 mn
	Left rear			6 mn
D	Right rear			6 mn
	Spare	Yes		
	Suspension			
	Suspension performance	V		
	Steering performance	V		
	Shock absorbers	1		
/	Air Conditioning / Heater			
	Operation	V		
5				
	Electrical / Accessories			
	Head lights	1		
	Tail lights	/		
	Indicators	-		
	Dashboard warning lights		/	
	Wipers (front & rear)	/		
	Window winder FL	/		
	Window winder FR	/		
	Window winder RL	/		
	Window winder RR	/		
	Rear view mirrors	/		
	Radio (basic test only)	/		
	CD (basic test only)			1
	Number of keys	1		
o Kms	Central locking	1		
	Remote locking	1		
				_
	Sat. nav. (basic test only)			

		<u> </u>					
Make:	Mazda	Model:	CX-5				
Body Style:	SUV	Year:	2021				
Rego No.:	NZF272	Rego Expiry:	20 Dec 2025				
WoF Expiry:	09 Jan 2026	Odometer:	78,821 Kms				
Good No.:	26057605	VIN:	JM0KF2W7A00704629				
Next Service:	Due.	Service History:	Yes				
diagnostic testing und	only. Consideration is made	e for age and mileage. Pa een driven up to 50km/h	nrts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.				
Key							
	= Rust $C = C$						
D = Dent PT	= Paint defect $P = Pi$	n dent SC = Sto	ne Chips				
S SC W S SD D Note: some defects and blemishes may not be displayed in the diagram Body Inspection Comments RR Door seal torn.RF body seal not secure.							
Conditions Duri	ng Body Inspection		Dry				
Under Carriage	e and Under Bonnet	Inspection Comm	ents				
2Wheel drive.	ents						
Seats:	Good						
Carpets:							
Panels:	Good						
Dashboard: Good							
General Comments							
I Stop warning g	lowing.Battery weak.						
Road Condition	s During Test Drive	Dry					
Engine Timing I		Timing Chain					
Evidence of Can	n Belt Replacement	Yes	No Kms				

I have read and understood this condition guide:

Inspection Date: 20 Nov 2025

Inspected by:

Published by:

NAME

Rajesh Mayan

Rajesh Mayan

SIGNATURE