


Basic Condition Guide

Report ID:	26,059,534	Version:	3
Created:	05 Dec 2025		

Make:	KIA	Model:	Sportage			
Body Style:	SUV	Year:	2021			
Rego No.:	NRU73	Rego Expiry:	05 Jan 2026			
WoF Expiry:	02 Aug 2026	Odometer:	86,818 Kms			
Good No.:	26059534	VIN:	KNAPR81CSM7974098			
Next Service:	89260	Service History:	Yes			
Note: This report is not a warranty						
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Windscreen stone chips.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

4Wheel drive

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Slight tyre noise.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Ch	ain	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Rajesh Mayan			
Published by:	Ben Nicholson			

I have read and understood					
this condition quide:					

Inspection Date: 27 Nov 2025

NAME				

	OK	Requires Attention	
Engine			,
Oil level	1		
Smoke & fumes	V		
Engine performance	•		
Noise			
Coolant condition	\(\tau \)		
Cooling performance	V		
Radiator / Hoses (visual)	/		
Transmission		<u> </u>	
Operation	/		
Noise	_		
Clutch			
CV joints	_		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	<i>\sqrt{\sq}}}}}}}}}}}}}} \sqite\septionup\sign{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}} \sqrt{\sq}}}}} \sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}} \sqite\septintite\septionup\sint{\sintexian}}}}}} \sqite\septintite\sin{</i>		
Tyres (lowest observed tread d	epth of	tvres)	
Left front	Сригог		3.0 mm
Right front			3.0 mm
Left rear			3.0 mm
Right rear			1.0 mm
Spare	Yes		
Suspension	100		
Suspension performance	J		
Steering performance	<i>y</i>		
Shock absorbers	<i>J</i>		
Air Conditioning / Heater			
Operation	/	l	
Electrical / Accessories			
Head lights	/	1	
3	· ·		
Tail lights Indicators	·/		
	V		
Dashboard warning lights	~		
Wipers (front & rear) Window winder FL	<i>'</i>		
Window winder FR Window winder FR			
Window winder FR Window winder RL	V		
	<i>'</i>		
Window winder RR			
Rear view mirrors	<i>\</i>		
Radio (basic test only)	•		
CD (basic test only)	2		
Number of keys		1	Ι
Central locking	V		
Remote locking	✓ ✓		
Sat. nav. (basic test only)	.,		
Reversing camera			<u> </u>

SIGNATURE			