

Basic Condition Guide


•	Report ID:	26,067,366	Version:	1
	Created:	27 Nov 2025		

Requires

Make:	Mazda	Model:	Axela			
Body Style:	Wagon	Year:	2013			
Rego No.:	PWY266	Rego Expiry:	23 Feb 2025			
WoF Expiry:	24 Nov 2026	Odometer:	90,995 Kms			
Good No.:	26067366	VIN:	7AT0C13JX23101035			
Next Service: 57,000 Kms Service History: No						
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

LH headlight cracked.

Tyre repair kit instead of spare wheel, missing jack.

RH tailgate taillight cracked.

Front bumper grill cracked.

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Engine oil level below minimum on dipstick.

Coolant reservoir level below minimum line.

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Troy Smith	
Published by:	Troy Smith	
Inspection Date:	27 Nov 2025	

I	have	read	and	und	lers	tood	
t	his co	nditi	on c	uide	2:		

NAME			

	OK	Attention	N/A
Engine			
Oil level		'	
Smoke & fumes	•		
Engine performance	/		
Noise	V V V		
Coolant condition	/		
Cooling performance	•		
Radiator / Hoses (visual)	•		
Transmission			
Operation	✓		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread de	epth of	tyres)	
Left front			6 mm
Right front			6 mm
Left rear		3	3.5 mm
Right rear			1.5 mm
Spare	N/A		
Suspension			
Suspension performance	/		
Steering performance	<i>'</i>		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	✓		
Window winder RR	1		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	1		
Central locking	•		
Remote locking	•		
Sat. nav. (basic test only)			'
Reversing camera			

SIGNATURE		