


Make:	Mazda	Model:	Axela
Body Style:	Hatchback	Year:	2009
Rego No.:	PLW617	Rego Expiry:	
WoF Expiry:	22 Aug 2025	Odometer:	130,131 Kms
Good No.:	26068294	VIN:	7AT0C13JX22100299
Next Service:	138,400 Kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Front bumper needs refitted.  
Crack in LH mirror indicator lens.  
LR reflector cracked.

Conditions During Body Inspection

Dry

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

Seats:	Poor, Burn hole in LF seat
Carpets:	Good
Panels:	Average
Dashboard:	Average, Steering wheel peeling

## General Comments

Low oil level. Ac not cold.  
Jack missing.  
RR window master switch fail.  
Space saver fitted on RF (Actual wheel in boot.)

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Caleb Spicer Lee
Published by:	Caleb Spicer Lee
Inspection Date:	31 Oct 2025

Report ID:	26,068,294	Version:	1
Created:	31 Oct 2025		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			5.5 mm
Right front			2 mm
Left rear			1 mm
Right rear			1.5 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation		✓	
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR		✓	
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide: \_\_\_\_\_

NAME

SIGNATURE