

Basic Condition Guide

| Report ID: | 26,068,327 | Version: | 4 |
|------------|-------------|----------|---|
| Created: | 10 Nov 2025 | | |


| Make: | Mazda | Model: | CX-5 |
|---------------|-------------|------------------|-------------------|
| Body Style: | SUV | Year: | 2022 |
| Rego No.: | NZR159 | Rego Expiry: | 13 Jan 2026 |
| WoF Expiry: | 24 Nov 2026 | Odometer: | 55,589 Kms |
| Good No.: | 26068327 | VIN: | JM0KF4WLA00705188 |
| Next Service: | 62,500 Kms | Service History: | Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

LH mirror surround scratched

| Conditions During Body Inspection | Dry |
|--|------|
| Under Carriage and Under Bonnet Inspection Comm | ents |

| Interior Comments | | |
|-------------------|------|--|
| Seats: | Good | |
| Carpets: | Good | |
| Panels: | Good | |
| Dashboard: | Good | |
| General Comments | | |

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|----------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: Caleb Spicer Lee | | |
| Published by: | Shanna Bullion | |
| Inspection Date: | 03 Nov 2025 | |

| | ОК | Requires Attention | N/A |
|--------------------------------|-------------------|-----------------------|--------|
| Engine | | | |
| Oil level | / | | |
| Smoke & fumes | / | | |
| Engine performance | / | | |
| Noise | \(\frac{1}{V} \) | | |
| Coolant condition | / | | |
| Cooling performance | / | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | V | | |
| Noise | / | | |
| Clutch | | | 1 |
| CV joints | / | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | 1 | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 3 | 3.0 mm |
| Right front | | | 2.5 mm |
| Left rear | | | 2.5 mm |
| Right rear | | | 2.5 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | V | | |
| Steering performance | / | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | V | | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | V | | |
| Indicators | V | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | V | | |
| Window winder FL | ~ | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | / | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | | | ~ |
| Number of keys | 2 | | |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | 1 | | |
| Reversing camera | / | | |
| | | | |

I have read and understood this condition guide:

NAME