

# **Basic Condition Guide**


Report ID:	26,068,554	Version:	2
Created:	20 Nov 2025		

OK Attention N/A  Engine  Oil level  Smoke & fumes  Engine performance  Noise  Coolant condition  Cooling performance  Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch  CV joints
Oil level  Smoke & fumes  Engine performance  Noise  Coolant condition  Cooling performance  Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch
Engine performance  Noise  Coolant condition  Cooling performance  Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch
Noise  Coolant condition  Cooling performance  Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch
Noise  Coolant condition  Cooling performance  Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch
Coolant condition  Cooling performance  Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch
Cooling performance  Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch
Transmission Operation Noise Clutch
Operation
Noise V
Clutch
CV joints 🗸
, , , , , , , , , , , , , , , , , , , ,
Wheel bearings 🗸
Brakes
Performance 🗸
Hand brake
Tyres (lowest observed tread depth of tyres)
Left front 5.5 m
Right front 6.0 m
Left rear 3.0 m
Right rear 3.0 m
Spare Yes
Suspension
Suspension performance 🗸
Steering performance 🗸
Shock absorbers 🗸
Air Conditioning / Heater
Operation 🗸
Electrical / Accessories
Head lights 🗸
Tail lights
Indicators 🗸
Dashboard warning lights 🗸
Wipers (front & rear)
Window winder FL 🗸
Window winder FR
Window winder RL
Window winder RR
Rear view mirrors
Radio (basic test only)
CD (basic test only)
Number of keys 2
Central locking 🗸
Remote locking 🗸
Sat. nav. (basic test only)
Reversing camera

Make:	Hyundai	Model:	lload
Body Style:	Van	Year:	2016
Rego No.:	KBN275	Rego Expiry:	19 Dec 2025
WoF Expiry:	11 Sep 2026	Odometer:	161,843 Kms
Good No.:	26068554	VIN:	KMFWBX7KLGU824034
Next Service:	172,000 Kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Tailgate seal damaged. Rear window scratched.

Windscreen molding missing.

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Commer	nts

Engine oil leak.

Interior Comments				
Seats:	Good			
Carpets: Average, FR carpet torn				
Panels:	Average			
Dashboard: Average				

### **General Comments**

Radio not picking up stations.

Driveline whine especially in third gear.

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Caleb Spicer Lee		
Published by:	blished by: Kate Gibson		
Inspection Date:	12 Nov 2025		

I have read and understood
this condition guide:

NAME			

SIGNATURE		