

Report ID:	26,068,577	Version:	1
Created:	12 Nov 2025		

Иake:	Skoda	Model:	Yeti
Body Style:	suv	Year:	2014
Rego No.:	HLY481	Rego Expiry:	09 Sep 2026
WoF Expiry:	10 Jun 2026	Odometer:	223,458 Kms
Good No.:	26068577	VIN:	TMBMD75L2E6012625
Next Service:	231,000 Kms	Service History:	No
agnostic testing un		een driven up to 50km/	Parts have not been dismantled or h from cold. The Vendor recommends a or an additional charge.
	= Rust C = C	rack *= Deca	ls W = Significant scuffs
= Dent PT	= Paint defect $P = Pi$	in dent SC = Stor	3
SPSC	SI	D SC S SC	SSC
0100			
	(M)-		S SC
s sc 1			
J	18		
	M = M		s sc
s sc			
			SSC
SC	S	P SC P SC	S PSC
		1 00	
ote: some defects a	and blemishes may not be	displayed in the diagra	ım

Front bumper lower grill damaged/needs refitted.

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Engine oil leak.

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Mirrors don't retract.

Minor fraying on drivers seatbelt.

	Road Conditions During Test Drive		Dry		
	Engine Timing Mechanism		Cambelt		
	Evidence of Cam Belt Replacement		Yes	V No	Kms
	Inspected by:	Troy Smith			
	Published by:	Troy Smith			
	Inspection Date:	12 Nov 2025			

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\xi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\xi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\ti}}\\ \tittt{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\text{\texi}\tiliex{\text{\tin}\tiliex{\text{\text{\texi{\text{\text{\text{\texi}\text{\text{\texi}\tiliex{\text{\til\titt{\text{\texi}\tiliex{\texi{\texi}\tiliex{\tiliex{\texi{\texitilex{\tii}\tiint{\tii}\tiint{\tiint{\texi{\texi{\texi{\tii}}\xii}		
Radiator / Hoses (visual)	/		
Transmission		l	
Operation	V		
Noise	/		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front	•		6 mm
Right front			7 mm
Left rear			2.5 mm
Right rear			3 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	V		
Shock absorbers			
Air Conditioning / Heater		l	
Operation			
Electrical / Accessories			
Head lights	V		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	·		
Window winder FL	~		
Window winder FR	·		
Window winder RL	·		
Window winder RR	·		
Rear view mirrors	=		
Radio (basic test only)	/		
CD (basic test only)	~		
Number of keys	1	l	Ь
Central locking	· /		
Remote locking	· /		
Sat. nav. (basic test only)	•		
Reversing camera			
			<u> </u>

I have read and understood this condition guide:

NAME SIGNATURE