

•	Report ID:	26,068,888	Version:	2
	Created:	28 Nov 2025		

		Poci	c Condition Guide	Report ID:	20,000,000	ve	rsion: 2	
	ntuet	S Dasi	——————————————————————————————————————	Created:	28 Nov 2025			
Make:	Renault	Model:	Master				Requires	
Body Style:	Van	Year:	2019			OK	Attention	N/A
Rego No.:	MAH20	Rego Expiry:	25 Dec 2025	Engine				1
WoF Expiry:	02 Mar 2026	Odometer:	167,311 Kms	Oil level		1		-
Good No.:	26068888	VIN:	VF1MAFFVC60922772	Smoke & f		<i>V</i>	<u> </u>	+
Next Service:	159,855 Kms	Service History:	No	Engine pe	rtormance	1		+
Note: This report is	s not a warranty	,		Noise Coolant co	andition	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						V		+
					erformance	V		┼
Key					Hoses (visual)			
= Scratch R = Rust C = Crack *= Decals W = Significant scuffs					Transmission Operation			
D = Dent $PT$ = Paint defect $P$ = Pin dent $SC$ = Stone Chips						7		┼─
SC	P	sc sc		Noise Clutch		-		-
								1
	(O)=		$(\bigcirc)$	CV joints	win as	1		<b>                                     </b>
		<u>'</u>		Wheel bea	irings		<u> </u>	
			HIV	Performan	250	V	l	Т
$\mathcal{M}$			SC	Hand brak		1		$\vdash$
							turos)	
SC				Left front	es (lowest observed tread depth of tyres)			4.5 mm
				Right front	<u> </u>			5.0 mm
				Left rear	<u> </u>			7.5 mm
SC		SC P SC	SC	Right rear				3.5 mm
Nata and data		diambarradia tha dia arra		Spare		Yes		
	s and blemishes may not be ion Comments	displayed in the diagra	am 	Suspension	on .	100		
Paint defect or				•	n performance	· /		
				•	erformance	1		$\vdash$
				Shock abs		1		+-
Conditions Du	ıring Body Inspection		Dry		tioning / Heater		1	
	ge and Under Bonnet	Inspection Comm		Operation			· ·	
Officer Curria	ge and onder bonner	mspection comm			/ Accessories			
				Head light		V		Τ
				Tail lights		1		+-
Interior Com	ments			Indicators		1		$\vdash$
Seats:	Poor, FR seat torn	า			d warning lights	· /		+
Carpets: Good			Wipers (fro		· /	1	+	
Panels:	Good			Window w		1		+-
Dashboard:	Average, Glovebo	ox doesn't stav cl	osed	Window w		· /	<u> </u>	+-
General Com		decent day on		Window w				\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Tow bar tongue				Window w				<del>-</del>
Ac not cold.	- <del></del> g.			VVIIIGOVV VV	macrim		-	+-

Road Condition	s During Test Drive	Dry	
Engine Timing N	Mechanism	Timing Chain	
Evidence of Can	n Belt Replacement	Yes No Kms	
Inspected by:	Caleb Spicer Lee		
Published by:	Kate Gibson		
Inspection Date:	24 Nov 2025		

have read and understood					
his condition quide					

Ac not cold.

NAME			

1

1 2

1

•

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera