

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 26,069,038  | Version: | 1 |
| Created:   | 26 Nov 2025 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Holden      | Model:           | Cruze             |
| Body Style:   | Hatchback   | Year:            | 2011              |
| Rego No.:     | GDJ94       | Rego Expiry:     | 29 Nov 2025       |
| WoF Expiry:   | 20 Nov 2025 | Odometer:        | 167,733 Kms       |
| Good No.:     | 26069038    | VIN:             | 6G1PE6E82CL600387 |
| Next Service: | Unknown     | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Missing jack. Front tyres wearing on inside edge.  
Front bumper fits poorly on LH side.  
LF, LR, RF tyres have gouged sidewalls.  
Drivers door check strap clicking.

Conditions During Body Inspection Dry

## Under Carriage and Under Bonnet Inspection Comments

Engine oil leaks.

## Interior Comments

|            |                                   |
|------------|-----------------------------------|
| Seats:     | Good                              |
| Carpets:   | Good                              |
| Panels:    | Average, centre console lid worn. |
| Dashboard: | Average, steering wheel worn.     |

## General Comments

Key remote worn.  
LH low beam and RH fog light not working.  
Noise in steering.

|                                   |                              |                             |     |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry                          |                             |     |
| Engine Timing Mechanism           | Timing Chain                 |                             |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by:                     | Troy Smith                   |                             |     |
| Published by:                     | Troy Smith                   |                             |     |
| Inspection Date:                  | 26 Nov 2025                  |                             |     |

|                                              | OK     | Requires<br>Attention | N/A |
|----------------------------------------------|--------|-----------------------|-----|
| Engine                                       |        |                       |     |
| Oil level                                    | ✓      |                       |     |
| Smoke & fumes                                | ✓      |                       |     |
| Engine performance                           | ✓      |                       |     |
| Noise                                        | ✓      |                       |     |
| Coolant condition                            | ✓      |                       |     |
| Cooling performance                          | ✓      |                       |     |
| Radiator / Hoses (visual)                    | ✓      |                       |     |
| Transmission                                 |        |                       |     |
| Operation                                    | ✓      |                       |     |
| Noise                                        | ✓      |                       |     |
| Clutch                                       |        |                       | ✓   |
| CV joints                                    | ✓      |                       |     |
| Wheel bearings                               | ✓      |                       |     |
| Brakes                                       |        |                       |     |
| Performance                                  | ✓      |                       |     |
| Hand brake                                   | ✓      |                       |     |
| Tyres (lowest observed tread depth of tyres) |        |                       |     |
| Left front                                   | 4 mm   |                       |     |
| Right front                                  | 4 mm   |                       |     |
| Left rear                                    | 5.5 mm |                       |     |
| Right rear                                   | 6 mm   |                       |     |
| Spare                                        | Yes    |                       |     |
| Suspension                                   |        |                       |     |
| Suspension performance                       | ✓      |                       |     |
| Steering performance                         | ✓      |                       |     |
| Shock absorbers                              | ✓      |                       |     |
| Air Conditioning / Heater                    |        |                       |     |
| Operation                                    | ✓      |                       |     |
| Electrical / Accessories                     |        |                       |     |
| Head lights                                  |        | ✓                     |     |
| Tail lights                                  | ✓      |                       |     |
| Indicators                                   | ✓      |                       |     |
| Dashboard warning lights                     | ✓      |                       |     |
| Wipers (front & rear)                        | ✓      |                       |     |
| Window winder FL                             | ✓      |                       |     |
| Window winder FR                             | ✓      |                       |     |
| Window winder RL                             | ✓      |                       |     |
| Window winder RR                             | ✓      |                       |     |
| Rear view mirrors                            | ✓      |                       |     |
| Radio (basic test only)                      | ✓      |                       |     |
| CD (basic test only)                         | ✓      |                       |     |
| Number of keys                               | 1      |                       |     |
| Central locking                              | ✓      |                       |     |
| Remote locking                               | ✓      |                       |     |
| Sat. nav. (basic test only)                  | ✓      |                       |     |
| Reversing camera                             |        | ✓                     |     |

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_