

## **Basic Condition Guide**

•	Report ID:	26,069,157	Version:	1	
	Created:	03 Dec 2025			

**Engine** Oil level

Noise

Smoke & fumes Engine performance

Coolant condition

ОК

1

Requires

Attention


N/A

Holden	Model:	Commodore
Wagon	Year:	2020
MQD230	Rego Expiry:	09 Jan 2026
13 Nov 2026	Odometer:	270,333 Kms
26069157	VIN:	W0VZM8EC6K1073132
285,000 Kms	Service History:	No
	Wagon MQD230 13 Nov 2026 26069157	Wagon         Year:           MQD230         Rego Expiry:           13 Nov 2026         Odometer:           26069157         VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

#### **Body Inspection Comments**

Holes drilled in front and rear bumpers. 4 additional aerial ports and cut electrical

harness on roof. Spare wheel needs secured. Drivers door check strap clicking. Drivers door seal torn.

Moisture in RH taillight. Both sills dented.

**Conditions During Body Inspection** Wet **Under Carriage and Under Bonnet Inspection Comments** 

# RH outer CV boot leaking

Minor AC oil leak.

	Interior Comments		
Seats: Good  Carpets: Average, holes drilled in passenger footwell.  Panels: Average, holes drilled in centre console.		Good	
		Average, holes drilled in passenger footwell.	
		Average, holes drilled in centre console.	
	Dashboard:	Average, holes drilled, steering wheel worn.	
ĺ	Canaval Comments		

Road Conditions During Test Drive		Dry
Engine Timing I	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Troy Smith	
Published by:	Troy Smith	
Inspection Date:	03 Dec 2025	

have read and understood			
this condition guide:	NAME		

Radiator / Hoses (visual)	•			
Transmission				
Operation	/			
Noise	•			
Clutch				<b>/</b>
CV joints	/			
Wheel bearings	/			
Brakes				
Performance	•			
Hand brake	•			
Tyres (lowest observed tread de	epth of	tyres)		
Left front			3.5	mn
Right front			4	mn
Left rear		2	2.5	mn
Right rear			4	mm
Spare	Yes			
Suspension				
Suspension performance	1			
Steering performance	1			
Shock absorbers	/			
Air Conditioning / Heater				
Operation	•			
Electrical / Accessories				
Head lights	•			
Tail lights	•			
Indicators	<b>/</b>			
Dashboard warning lights	•			
Wipers (front & rear)	•			
Window winder FL	•			
Window winder FR	•			
Window winder RL	•			
Window winder RR	•			
Rear view mirrors	/			
Radio (basic test only)	/			
CD (basic test only)				/
Number of keys	3			
Central locking	•			
Remote locking	•			
Sat. nav. (basic test only)				/
Reversing camera	/			