

Report ID:	26,069,306	Version:	1
Created:	07 Dec 2025		


Make:	Mercedes-Benz	Model:	C200
Body Style:	Sedan	Year:	2011
Rego No.:	PBZ981	Rego Expiry:	02 Feb 2026
WoF Expiry:	30 Oct 2025	Odometer:	161,013 Kms
Good No.:	26069306	VIN:	WDD2040482A589433
Next Service:	123,700 Kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

All tyres need replaced.

Conditions During Body Inspection

Dry

## Under Carriage and Under Bonnet Inspection Comments

Minor engine oil leak.

RL shock absorber leaking, dust cover loose.

## Interior Comments

Seats:	Average
Carpets:	Good
Panels:	Good
Dashboard:	Good, steering wheel wearing.

## General Comments

Radio infotainment control knob missing, radio buttons are unresponsive.

Reverse camera not working.

Suspension knock.

Service overdue message on dash.

Not test driven as not road worthy.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Troy Smith		
Published by:	Troy Smith		
Inspection Date:	07 Dec 2025		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			0 mm
Right front			1.4 mm
Left rear			0 mm
Right rear			1.5 mm
Spare		No	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers		✓	
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera		✓	

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_