


Make:	Holden	Model:	Colorado 7
Body Style:	SUV	Year:	2014
Rego No.:	PWM945	Rego Expiry:	27 Jul 2024
WoF Expiry:	22 Apr 2026	Odometer:	111,196 Kms
Good No.:	26069766	VIN:	MMU156MH0DH804764
Next Service:	101,000 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

LH taillight, LH rear reflector, and RH tailgate taillight have dirt/moisture inside.

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

No oil on engine oil dipstick.

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Average, steering wheel worn.

General Comments

Rear window washer not spraying.

LH brake light not working.

Both reverse lights not working.

Brakes are pulsating.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Inspected by:	Troy Smith
Published by:	Troy Smith
Inspection Date:	18 Jan 2026

I have read and understood
this condition guide:

NAME _____

Report ID:	26,069,766	Version:	1
Created:	18 Jan 2026		

	OK	Requires Attention	N/A
Engine			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance		✓	
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front		5 mm	
Right front		4.5 mm	
Left rear		4 mm	
Right rear		4.5 mm	
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)			✓
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

SIGNATURE _____