

## **Basic Condition Guide**

•	Report ID:	26,069,895	Version:	1
	Created:	22 Dec 2025		

	orner		Condition Guide	Created: 22	2 Dec 2025			
Make:	Nissan	Model:	Navara		OK	Requires Attention	N/A	
Body Style:	Utility	Year:	2021	Engine	Attention	IN/A		
Rego No.:	NQL512	Rego Expiry:	25 Jan 2026	Oil level				
WoF Expiry:	26 Jul 2026	Odometer:	65,549 Kms	Smoke & fumes			-	
Good No.:	26069895	VIN:	MNTCBND23A0006410				-	
Next Service:	76,400 Kms	Service History:	Yes	Engine performance Noise			-	
Note: This report is not a warranty					tion V		-	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a ull mechanical inspection prior to purchase and this can be arranged for an additional charge.							-	
							<u> </u>	
Key								
S = Scratch $R = Rust$ $C = Crack$ $* = Decals$ $W = Significant scuffs$ $D = Dent$ $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$					Transmission Operation			
							├	
sc		sc	Noise	<i>'</i>	-	<u> </u>		
			Clutch					
			(0)	CV joints	<i>'</i>	-	<u> </u>	
SC (				Wheel bearings				
M	18			Brakes				
				Performance	· ·		<u> </u>	
			Hand brake	<i>'</i>				
sc				Tyres (lowest observed tread depth of tyres)				
			C D DT CC	Left front 7			7 m	
S D PT SC						6.5 mn		
	$\leq$			Left rear		7 m		
					Right rear		7 m	
ote: some defects	and blemishes may not be	e displayed in the diagra	Spare Yes					
Body Inspection	on Comments			Suspension				
	held by bungee cords	5.		Suspension pe	erformance 🗸			
Crack in windso RF step plate w				Steering perfo	rmance 🗸			
iti step plate w	om.			Shock absorbe	ers 🗸			
Conditions Dur	ring Body Inspection		Air Conditioning / Heater					
Under Carriag	e and Under Bonnet	Inspection Comm	Operation 🗸					
				Electrical / Ac	cessories			
				Head lights	V			
				Tail lights	V			
Interior Comm	nents			Indicators	V			
Seats:	Good			Dashboard wa	rning lights			
Carpets:	Good			Wipers (front &	3 3 11			
Panels:	Good		Window winde		+			
Dashboard:	Good	Window winde			<u> </u>			
General Comn				Window winde			<u> </u>	
Certain Contin				Window winde			<u> </u>	
				Rear view mirr			-	
							<del>                                     </del>	
Deed Condition	a Demin a Test Di	Dn/		Radio (basic te	,,		<del>  .,</del>	
Road Conditions During Test Drive Dry  Timing Chain					-			
Engine Timing Mechanism Timing Chain					/s 2		т —	
Evidence of Cam Belt Replacement Yes No Kms					g <b>/</b>		$oxed{oxed}$	

I have read and understood this condition guide:

Inspection Date: 22 Dec 2025

Inspected by:

Published by:

NAME

Caleb Spicer Lee

Caleb Spicer Lee

SIGNATURE

Remote locking

Reversing camera

Sat. nav. (basic test only)

1