


Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2018
Rego No.:	LPR562	Rego Expiry:	26 Mar 2026
WoF Expiry:	14 Jan 2027	Odometer:	194,684 Kms
Good No.:	26069980	VIN:	MPBUMFF50JX174396
Next Service:	207,000 KMS	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Dent in LH cab corner.    LH mirror repeater cracked.  
 Crack in windscreen.    RF door seal torn.  
 Paint defect on canopy.    RF step plate worn.  
 Canopy carpet lining burnt.    Rear bumper pushed in.

Conditions During Body Inspection    Dry

**Under Carriage and Under Bonnet Inspection Comments**

**Interior Comments**

Seats: Poor, RF seat torn  
 Carpets: Good  
 Panels: Good  
 Dashboard: Average, Steering wheel worn

**General Comments**

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Caleb Spicer Lee
Published by:	Kate Gibson
Inspection Date:	23 Dec 2025

I have read and understood  
 this condition guide:

NAME \_\_\_\_\_

Report ID:	26,069,980	Version:	2
Created:	14 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	5.0	mm	
Right front	5.5	mm	
Left rear	5.5	mm	
Right rear	5.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	3		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

SIGNATURE \_\_\_\_\_