


Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2020
Rego No.:	MYJ412	Rego Expiry:	12 Apr 2026
WoF Expiry:	14 Jul 2026	Odometer:	148,774 Kms
Good No.:	26070207	VIN:	MMAJLKK10LH015449
Next Service:	160,000 kms	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Crack in windscreen , left front step plate worn, scratches right inner wheel arch  
 Chips and scratches left rear step plate, chips and scratches left cab corner,  
 chips and scratches right cab corner,  
 Chips right rear step plate, right front step plate worn

Conditions During Body Inspection      Wet

**Under Carriage and Under Bonnet Inspection Comments**

Belt Noise in pulley area when cold

**Interior Comments**

Seats: right front seat base pad torn

Carpets: right front carpet torn

Panels: Good

Dashboard: Good

**General Comments**

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Dean Sinclair
Published by:	Dean Sinclair
Inspection Date:	15 Jan 2026

I have read and understood  
 this condition guide:

NAME \_\_\_\_\_

Report ID:	26,070,207	Version:	1
Created:	15 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		3 mm	
Right front		4.5 mm	
Left rear		4 mm	
Right rear		4.5 mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

SIGNATURE \_\_\_\_\_