


Make:	Great Wall	Model:	Steed
Body Style:	Utility	Year:	2018
Rego No.:	RLS338	Rego Expiry:	30 Aug 2025
WoF Expiry:	12 Jun 2026	Odometer:	82,345 Kms
Good No.:	26070367	VIN:	LGWDBE18XHB611027
Next Service:	Unknown	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Both mirror indicator lens cracked.

LR flare needs refitted.

Front bumper needs refitted.

Conditions During Body Inspection      Dry

**Under Carriage and Under Bonnet Inspection Comments**

Engine oil leak.

**Interior Comments**

Seats:	Good
Carpets:	Poor, RF carpet torn
Panels:	Good
Dashboard:	Good

**General Comments**

Tools/Jack missing.

LF fog light fail.

LH mirror horizontal adjustment reversed.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
	Kms
Inspected by:	Caleb Spicer Lee
Published by:	Caleb Spicer Lee
Inspection Date:	20 Jan 2026

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	26,070,367	Version:	1
Created:	20 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	6.5 mm		
Right front	11.5 mm		
Left rear	6.5 mm		
Right rear	6.5 mm		
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE \_\_\_\_\_