

Report ID:	26,071,491	Version:	1
Created:	24 Feb 2026		


Make:	Holden	Model:	Colorado
Body Style:	Utility	Year:	2020
Rego No.:	NAT69	Rego Expiry:	01 Sep 2026
WoF Expiry:	08 Sep 2026	Odometer:	196,179 Kms
Good No.:	26071491	VIN:	MMU148DK0LH637172
Next Service:	210,000 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Holes drilled in front bumper, 3 additional aerial bases and cut electrical harness on roof. Front bumper is loose on RH side.
 FR door seal torn. FR sill step plate worn.
 LF tyre worn to second layer on outside edge.

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Engine cover missing.
 Front undertray damaged.

Interior Comments

Seats:	Good
Carpets:	Average, holes drilled in passenger footwell.
Panels:	Average, holes drilled, centre console lid worn.
Dashboard:	Average, metal plate in dash.

General Comments

LH number plate light not working, message on dash.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Kms
Inspected by:	Troy Smith
Published by:	Troy Smith
Inspection Date:	24 Feb 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			3.5 mm
Right front			3 mm
Left rear			7.5 mm
Right rear			6.5 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	3		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____