

I have read and understood this condition guide.

Report ID: 26,073,969 2 Version: 10 Mar 2025 Created:

Signature: .....

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2022	Registration:	PBZ698	Reg Expiry:	31 Mar 2025	Engine			I
WoF Expiry:		Odometer:	98,123 Kms	Good No:	26073969	Oil level	~		
VIN:	MPBUMFF60MX372633	Next Service:	105,500 kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	SC S	-0	S SC S P SC	-161-	S P W SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent S = suct S = S C S = S C C C S = S C C C C C C C C C C C C C C C C C							Operation 🖌		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals PSC PIP						Wheel bearings	~		
SC = stone chips							Brakes		
W = significant scuffs S SC P SC S SC S P W SC						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	of tyre	) (
Step plates scratches/chipped									 
Minor dents left cant rail Right tail light cracked						Right front	10		 
Right tail lig						Left rear	5.		mm
Conditions During Pody Inspection						Right rear			mm
Conditions During Body Inspection: Dry						Right rear 3.5 mm   Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	v		
						Operation V			
Interior Comments						Electrical / Accessories			
						Head lights	~		
Jeals	Good					Tail lights	~		
Carpets	Good						~		
Demela						Dashboard warning lights	~		
Panels	Minor scra	atches left rear do	oor trim			Wipers (front & rear)	~		
Dashboa	rd Minor scra	atches centre con	sole			Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
	—					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	•		~
						Number of keys	2		<u> </u>
Road Conditions During Test Driver Drev						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt Sat. Nav. (basic test only)							~		
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		
							-		
Inspected by: Dean Sinclair Date: 10 Mar 2025									

Name: .....