

Basic Vehicle Condition Guide

Report ID: 26,074,447


Version: 2

Created: 03 Apr 2025

Make: Model: Mazda CX-5 **Body Style:** SUV Year: 2019 Registration: MCT50 Reg Expiry: 02 May 2025 WoF Expiry: **Odometer: Good No:** 17 Apr 2026 93,097 Kms 26074447 VIN: JM0KF4W2A0031154! Next Service: 95,000kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Under Carriage & Under Bonnet Inspection Comments

Conditions During Body Inspection:

<u>Interior Comments</u>		
Seats	Good	
Carpets	Average	
Panels	Scuffs in cargo area.	
Dashboard	Good	

Dry

General Comments

AWD diesel auto SUV.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Daryll Timms Date: 17 Mar 2025

Name:

Pacc	Fail	N/A
1 033	ı all	19/74
V		
~		
~		
~		
'		
~		
~		
		I
~		
~		
		~
~		
~		
		1
~		
~		
d depth	of tyre	es)
· ·		mm
5	5.0	
4	.0	mm
5.0		mm
	Yes	
~		
~		
~		
	l .	
~		
	i	
~		
✓ ✓		
~		
✓ ✓		
\(\times \)		
V V V V V		
\(\times \) \(\t		
V V V V		
V V V V V V V		
V V V V V V V V		
V V V V V V		
V V V V V V		v
V V V V V V		V
V V V V V V		v
V V V V V V V V V V V V V V V V V V V		· · · · · · · · · · · · · · · · · · ·
	5 5 4	V

Signature: