

Report ID: 26,074,701 3 Version: 20 Mar 2025 Created:

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2023	Registration:	PRP212	Reg Expiry:	18 Jan 2026	Engine			
WoF Expiry:	19 Jan 2026	Odometer:	33,720 Kms	Good No:	26074701	Oil level	~		
VIN:	JTFTA3AP908049715	Next Service:	45,000 kms	Service History	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for any and miles	a Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and th	nis can be arranged	for an additional c	harge.	Coolant condition	~		
					6.0.6	Performance	~		
Key:	S	-0	S SC SC	<u> –</u> –	S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation 🖌			
R=rust						Noise	~		
PT = paint defect C = crack						Clutch	~		
P = pin dent						CV joints	•		~
* = decals SC QQ						Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs S D P						Performance	~		
		Note: com			layed in the diagram	Hand Brake	~		
Body Insp	ection Comments	Note. son	le délects à Dieffilsi	les may not be disp	layed in the diagram		•	- f t 1 1 1 - 1	
Minor dents right A pillar						Tyres (lowest observed tread depth of tyres)			
RF sill step plate worn						Left front	4		mm
Dents cargo area right wheel arch						Right front	4		mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & Under BOI	metinspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	LF seat sta	ined				Head lights	~		
Carpets	Good					Tail lights	~		
	0000					Indicators	~		
Panels	RR interior	r door trim dama	ged. Scratches carge	o area inner frame		Dashboard warning lights	~		
Dashboa	rd Card					Wipers (front & rear)	~		
Dastibua	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
Remote locking							~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Dean Sinclair Date: 20 Mar 2025									

I have read and understood this condition guide.

Name:

Signature: