

Report ID: 26,075,972 2 Version: 29 Apr 2025 Created:

Signature: .....

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2021		NHA339	Reg Expiry:	15 May 2025	Engine			
WoF Expiry:		Odometer:	77,493 Kms	Good No:	26075972	Oil level	~		
VIN:	JSAAZC83S00402673	Next Service:	,	Service Histor		Smoke & fumes	~		
	55, 4 (2005)00 102075					Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
				_		Performance	<b>v</b>		
Key:	SC	-0	SC SC			Radiator / Hoses (visual)	<b>v</b>		
S = scratch	Se	0		105	$\mathbf{x}$	Transmission	~		
D = dent	s sc all			1 - L	P SC				
R = rust				10		Operation Noise	<b>v</b>		
PT = paint defe C = crack	ect M			+	SC		~		
C = Crack P = pin dent	LHC					Clutch			~
* = decals	PSC PSC			SI_		CV joints Wheel bearings	~		
SC = stone chips						<u>_</u>	, , , , , , , , , , , , , , , , , , ,		
W = significant scuffs						Brakes			1
		Nataraa				Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake		<i>с</i> .	Ļ
Right cant rail pin dented.						Tyres (lowest observed tread depth of tyres)			
	· ·					Left front	5		mm
						Right front		5	mm
r						Left rear	6		mm
Conditions During Body Inspection: Wet						Right rear	6	6 mr	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & Under BUI	metinspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Average					Tail lights	~		
	Avelage					Indicators	~		
Panels	Holes in ca	argo area side pa	nels.			Dashboard warning lights	~		
Dashboa	rd Card					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
		<b></b>	<u></u>			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Lewis Dolamore Date: 29 Apr 2025									

I have read and understood this condition guide.

Name: .....