

Report ID: 26,076,329 7 Version: 29 May 2025 Created:

Make:	Mazda	Model:	CX-5	Body Style:	SUV		Pass	Fail	N/A
Year:	2019	Registration:	MEY554	Reg Expiry:	17 Jun 2025	Engine	1		
WoF Expiry:	11 Jun 2026	Odometer:	177,521 Kms	Good No:	26076329	Oil level	~		
VIN:	JM0KF4WLA0030307{	Next Service:	185000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and tr	lis can be arranged to	or an additional C	narge.	Coolant condition	~		
	PT SC		SC S P SC		PT	Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	PW			10	Ell sc w	Operation	~		
PT = paint defe	ect NP	1			PT SC	Noise	~		
C = crack				\square	J III III	Clutch			~
P = pin dent	SD dk			SL-	7HHB	CV joints	~		
* = decals SC = stone chi		10		70	P SC	Wheel bearings	~		
W = significant scuffs						Brakes			
_	S W		S PT P SC		PT	Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			es)
						Left front	5.	.0	mm
						Right front	5.	.0	mm
						Left rear	4.	.5	mm
Conditions During Body Inspection:						Right rear	5.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Under Ca	irriage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		-
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (<u>Comments</u>					Window winder FR	~		
	<u>comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		-
						CD (basic test only) Number of keys	2		~
Road Conditions During Test Drive: Dry						Central locking Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	v		
Evidence of Cam Belt Replacement: Not Applicable Kms:							v		
		1				Reversing camera	~		
Inspected by: Chris McQuade Date: 28 May 2025									

I have read and understood this condition guide.

Name:

Signature: